

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

6541-6549 BRUSH STREET (APARTMENT BUILDING)

HABS No. MI-439

Detroit

Wayne County

Michigan

Jet Lowe, Photographer, 2003

MI-439-1      FRONT ELEVATION. THREE-STORY BRICK BUILDING WITH TWO LARGE ARCHED ENTRYWAYS. STREET FACADE HAS SEVERAL WINDOWS ON EACH FLOOR WITH ENLARGED BRACKET ELEMENT AND ANGULAR STONE MANTLE AND STONE SILL. SECOND FLOOR HAS THREE BAY WINDOWS PROTRUDING FROM THE FACADE. THE DECORATIVE CORNICE ON THE ROOF IS SUPPORTED BY SQUARE BRACKETS WITH A LINE OF DENTIL MOLDING UNDERNEATH. THERE HAS BEEN FIRE DAMAGE TO THE SECOND AND THIRD FLOORS.