

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MINN
10-WATO,
3-

200 Lewis Avenue North (House)
Lewis Avenue North Historic District
City of Watertown
Carver County
Minnesota

HABS No. MN-130

Documentation: 7 exterior photos (1990)
2 interior photos (1990)
2 photographic copies of historic photographs (ca. 1885)
~~14 data pages (1990)~~

Burt Levy, Photographer, August 1990

- MN-130-1 STREETScape, LOOKING SOUTHEAST: VIEW OF WEST FRONT, 200 LEWIS AVENUE NORTH ON LEFT, 112 AND 108 LEWIS AVENUE NORTH ON RIGHT
- MN-130-2 VIEW OF FRONT (WEST), LOOKING EAST
- MN-130-3 VIEW OF SOUTH SIDE, LOOKING NORTH
- MN-130-4 VIEW OF REAR (EAST), LOOKING WEST
- MN-130-5 VIEW OF NORTH SIDE AND NORTHEAST CORNER (room addition in foreground)
- MN-130-6 DETAIL: MAIN ENTRY AND PORCH, SOUTHWEST CORNER LOOKING NORTHEAST
- MN-130-7 DETAIL: NORTHWEST CORNER, SHOWING ENTRY TO WING, WINDOW, AND PORCH ORNAMENTATION
- MN-130-8 FIRST FLOOR: NORTH ROOM OF 1-1/2 STORY SECTION, LOOKING INTO SOUTHWEST ROOM
- MN-130-9 SECOND FLOOR: SOUTHEAST ROOM, LOOKING NORTH; STAIRWAY TO FIRST FLOOR VISIBLE TO RIGHT
- MN-130-10 Photographic copy of photograph (ca. 1885, original print in possession of Jim Cornell, Minneapolis, Minnesota). DISTANT VIEW OF REAR OF 108, 112, AND 200 LEWIS (200 is center house on the right edge of the photo; 112 and 108 are to its left)
- MN-130-11 Photographic copy of photograph (ca. 1885, original print in possession of Jim Cornell, Minneapolis, Minnesota). FRONT (WEST) BEFORE PORCH ADDITION