

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
MINN
67-LUV,
1-

Worthington and Sioux Falls Freight Depot
106 East Fletcher Street
Luverne
Rock County
Minnesota

HABS NO. MN-135

Documentation: 7 exterior photos (1992)
 1 interior photo (1992)
 15 data pages

Burt Levy, Photographer, February 1992
1101 Stinson Avenue
Minneapolis, Minnesota 55413

- MN-135-1 SETTING OF DEPOT. SUBJECT DEPOT AT FAR RIGHT, VIEW TO EAST
- MN-135-2 EAST GABLE END, VIEW TO WEST
- MN-135-3 NORTH SIDE, VIEW TO SOUTH
- MN-135-4 WEST END, VIEW TO EAST
- MN-135-5 SOUTH SIDE, VIEW TO EAST
- MN-135-6 DETAIL OF EAVE BRACKET, NORTH SIDE
- MN-135-7 DOOR, CENTER OF NORTH SIDE
- MN-135-8 INTERIOR, FROM NEAR WEST END DOOR, VIEW TO NORTHEAST