

HABS
MO,
48-INDEP,
3-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Harry S Truman House
(Harry S Truman National Historic
Site)
219 N. Delaware St.
Independence
Jackson County
Missouri

HABS No. MO-1175

Jack E. Boucher, Photographer, March 1983

- MO-1175-1 GENERAL VIEW OF NORTH (LEFT) AND WEST (RIGHT) FACADES
FROM NORTHWEST CORNER OF THE INTERSECTION OF DELAWARE
STREET AND TRUMAN ROAD
- MO-1175-2 WEST ELEVATION FROM THE EAST SIDE OF DELAWARE STREET
- MO-1175-3 GENERAL VIEW OF NORTH (LEFT) AND WEST (RIGHT) FACADES
FROM NORTHWEST SECTION OF THE WEST LAWN
- MO-1175-4 NORTH ELEVATION FROM THE NORTH LAWN
- MO-1175-5 SOUTH ELEVATION FROM THE SOUTH LAWN
- MO-1175-6 GENERAL VIEW OF WEST (FRONT) AND SOUTH (RIGHT) FACADES
FROM SOUTHWEST SECTION OF WEST LAWN.
- MO-1175-7 EAST ELEVATION FROM CENTER OF EAST LAWN
- MO-1175-8 GENERAL VIEW OF EAST FACADE FROM SOUTHEAST SECTION OF
SOUTHEAST LAWN
- MO-1175-9 SOUTHERN SECTION OF EAST ELEVATION FROM SOUTHEAST
CORNER OF EAST PORCH
- MO-1175-10 SOUTHERN SECTION OF WEST ELEVATION FROM CENTER OF WEST
LAWN
- MO-1175-11 SOUTHERN-MOST BAY OF WEST ELEVATION
- MO-1175-12 OBLIQUE VIEW FROM NORTHWEST OF SOUTHERN-MOST BAY OF
WEST ELEVATION
- MO-1175-13 OBLIQUE VIEW FROM SOUTHWEST OF SOUTH PORCH
- MO-1175-14 WEST PORCH

HARRY S TRUMAN HOUSE
HABS No. MO-1175
Index to Photographs (Page 2)

- MO-1175-15 GENERAL VIEW OF NORTHWEST CORNER OF HOUSE FROM NORTHWEST
CORNER OF WEST LAWN
- MO-1175-16 DETAIL OF WEST PORCH, LOOKING NORTH TOWARD TRUMAN ROAD
- MO-1175-17 DETAIL OF NORTHWEST CORNER OF WEST PORCH, SHOWING
DECORATIVE WOODWORK
- MO-1175-18 DETAIL OF BRACKET ON THE GABLE EAVE OF SOUTH FACADE

HABS
MO
48-INDEP
3

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

An addendum to
Harry S. Truman House
Harry S. Truman National Historic Site
219 North Delaware Street
Independence
Jackson County
Missouri

HABS No. MO-1175

The Piaget-van Ravenswaay Survey consists of a number of photographs, primarily of sites and structures in Missouri, which were taken before 1938 by Alexander Piaget and after that by Paul Piaget, both in conjunction with Charles van Ravenswaay. Photographs of buildings were incorporated into the HABS collection in 1985 by Laura Rupp and in 1986 by Deborah Fulton, HABS historians. A master list is available in the [REDACTED] records for MO-1800.

These photographs had facsimile negatives made in 1985 because of the non-archival condition of the original nitrate and di-acetate base negatives. The HABS reference photoprint is a contact print from the facsimile negative.

Piaget-van Ravenswaay photograph June 1946

MO-1175-19 FRONT FACADE

MO-1175-20 FRONT AND SIDE FACADES

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MO
48-INDEP,
3-

ADDENDUM TO:
HARRY S. TRUMAN HOUSE
Harry S. Truman National Historic Site
219 North Delaware Street
Independence
Jackson County
Missouri

HABS No. MO-1175
(page 4)

Photographs MO-1175-1 to MO-1175-20 were previously transmitted to the Library of Congress.

Jack E. Boucher, Photographer, March 1983

- MO-1175-21 LAUNDRY ROOM (002), BASEMENT, FROM WEST.
- MO-1175-22 NORTH CENTRAL ROOM (003), BASEMENT, FROM EAST
- MO-1175-23 NORTH CENTRAL ROOM (003), BASEMENT, DETAIL OF
ELECTRICAL WIRING ON CEILING NEAR ELECTRICAL POWER
BOX ON NORTH WALL
- MO-1175-24 FURNACE ROOM (004), BASEMENT, WEST WALL FROM
NORTHEAST
- MO-1175-25 SOUTHWEST ROOM (005), BASEMENT, FROM EAST
- MO-1175-26 SOUTHWEST ROOM (005), BASEMENT, SOUTHWEST CORNER
FROM EAST
- MO-1175-27 FOYER BY WEST DOOR TO OUTSIDE (102), FIRST FLOOR,
DETAIL OF DADO ON NORTH WALL FROM SOUTH
- MO-1175-28 CENTRAL HALL (103), FIRST FLOOR, OVERALL VIEW OF SOUTH
SECTION FROM NORTH
- MO-1175-29 CENTRAL HALL (103), FIRST FLOOR, EAST WALL & ENTRANCE
TO DINING ROOM FROM WEST
- MO-1175-30 CENTRAL HALL (103), FIRST FLOOR, DETAIL OF SOUTH
ENTRANCE FROM NORTHEAST
- MO-1175-31 CENTRAL HALL (103), FIRST FLOOR, DETAIL OF LAMP ON
STAIRCASE FROM NORTH

- MO-1175-32 LIVING ROOM (104), FIRST FLOOR, OVERALL VIEW FROM
NORTHEAST ENTRANCE
- MO-1175-33 LIVING ROOM (104), FIRST FLOOR, NORTH WALL &
NORTHWEST CORNER FROM SOUTHEAST
- MO-1175-34 LIVING ROOM (104), FIRST FLOOR, DETAIL OF SOFA & COFFEE
TABLE ALONG WEST WALL FROM EAST
- MO-1175-35 LIVING ROOM (104), FIRST FLOOR, OVERALL VIEW TO EAST
FROM WEST
- MO-1175-36 LIVING ROOM (104), FIRST FLOOR, DETAIL OF BOOKCASE
ALONG EAST WALL FROM WEST, DOORS CLOSED
- MO-1175-37 LIVING ROOM (104), FIRST FLOOR, DETAIL OF BOOKCASE
ALONG EAST WALL FROM WEST, DOORS OPEN
- MO-1175-38 LIVING ROOM (104), FIRST FLOOR, SOUTHWEST CORNER FROM
NORTHEAST
- MO-1175-39 LIVING ROOM (104), FIRST FLOOR, DETAIL OF TABLE IN
NORTHEAST CORNER FROM SOUTHWEST
- MO-1175-40 LIVING ROOM (104), FIRST FLOOR, DETAIL OF FIREPLACE &
PAINTING OF PRESIDENT HARRY S. TRUMAN ON SOUTH WALL
FROM NORTH
- MO-1175-41 LIVING ROOM (104), FIRST FLOOR, NORTHWEST CORNER FROM
SOUTHEAST
- MO-1175-42 GATES BEDROOM (105), FIRST FLOOR, NORTH WALL FROM
CENTER OF ROOM
- MO-1175-43 GATES BEDROOM (105), FIRST FLOOR, SOUTH SECTION FROM
WEST DOOR, NORTHWEST CORNER
- MO-1175-44 GATES BEDROOM (105), FIRST FLOOR, DRESSER ON EAST
SECTION OF NORTH WALL FROM CENTER OF ROOM
- MO-1175-45 GATES BEDROOM (105), FIRST FLOOR, DETAIL OF TOP OF
DRESSER ON WEST SECTION OF NORTH WALL

- MO-1175-46 GATES BEDROOM (105), FIRST FLOOR, DETAIL OF DRESSER ON EAST SECTION OF NORTH WALL
- MO-1175-47 GATES BATHROOM (106), FIRST FLOOR, OVERALL VIEW FROM NORTH
- MO-1175-48 GATES BATHROOM CLOSET (106-A), FIRST FLOOR, NORTH WALL FROM SOUTH
- MO-1175-49 FOYER BY SOUTHEAST DOOR TO OUTSIDE (107), FIRST FLOOR, DETAIL OF HAT & COAT RACK FROM SOUTHWEST
- MO-1175-50 PARLOR/MUSIC ROOM (108), FIRST FLOOR, EAST WALL FROM SOUTH ENTRANCE
- MO-1175-51 PARLOR/MUSIC ROOM (108), FIRST FLOOR, EAST WALL & NORTHEAST CORNER FROM SOUTHWEST
- MO-1175-52 PARLOR/MUSIC ROOM (108), FIRST FLOOR, EAST WALL, INCLUDING FIREPLACE & PAINTING OF MRS. BESS WALLACE TRUMAN, FROM NORTHEAST
- MO-1175-53 PARLOR/MUSIC ROOM (108), FIRST FLOOR, EAST WALL, INCLUDING FIREPLACE & PAINTING OF MRS. BESS WALLACE TRUMAN, FROM NORTHWEST
- MO-1175-54 PARLOR/MUSIC ROOM (108), FIRST FLOOR, OVERALL VIEW TO NORTH FROM SOUTH
- MO-1175-55 PARLOR/MUSIC ROOM (108), FIRST FLOOR, NORTHWEST CORNER FROM SOUTHEAST
- MO-1175-56 PARLOR/MUSIC ROOM (108), FIRST FLOOR, WEST WALL & DETAIL OF PIANO FROM SOUTHEAST
- MO-1175-57 PARLOR/MUSIC ROOM (108), FIRST FLOOR, DETAIL OF PIANO FROM SOUTHEAST
- MO-1175-58 PARLOR/MUSIC ROOM (108), FIRST FLOOR, DETAIL OF CHANDELIER IN CENTER OF CEILING FROM NORTHWEST
- MO-1175-59 LIBRARY (109), FIRST FLOOR, NORTH WALL FROM SOUTHWEST ENTRANCE

- MO-1175-60 LIBRARY (109), FIRST FLOOR, WEST WALL FROM EAST
- MO-1175-61 LIBRARY (109), FIRST FLOOR, SOUTH WALL FROM NORTH
- MO-1175-62 LIBRARY (109), FIRST FLOOR, EAST & SOUTH WALLS FROM DOOR IN NORTHWEST CORNER
- MO-1175-63 LIBRARY (109), FIRST FLOOR, NORTHEAST CORNER FROM SOUTHWEST
- MO-1175-64 LIBRARY (109), FIRST FLOOR, EAST WALL FROM WEST
- MO-1175-65 LIBRARY (109), FIRST FLOOR, EAST WALL FROM WEST
- MO-1175-66 LIBRARY (109), FIRST FLOOR, SOUTHEAST CORNER FROM NORTHWEST
- MO-1175-67 LIBRARY (109), FIRST FLOOR, SOUTH WALL FROM NORTH
- MO-1175-68 DINING ROOM (110), FIRST FLOOR, SOUTH & WEST WALLS FROM NORTH
- MO-1175-69 DINING ROOM (110), FIRST FLOOR, DETAIL OF CHINA CLOSET ALONG EAST WALL FROM SOUTHWEST
- MO-1175-70 DINING ROOM (110), FIRST FLOOR, DETAIL OF CHINA CLOSET ALONG EAST WALL FROM WEST
- MO-1175-71 DINING ROOM (110), FIRST FLOOR, SOUTH WALL WITH DETAIL OF EPERGNE FROM NORTHEAST
- MO-1175-72 DINING ROOM (110), FIRST FLOOR, DETAIL OF BUILT-IN CHINA CLOSET IN WEST WALL FROM EAST
- MO-1175-73 DINING ROOM (110), FIRST FLOOR, DETAIL OF FURNACE REGISTER ALONG WEST WALL FROM NORTHEAST
- MO-1175-74 DINING ROOM (110), FIRST FLOOR, DETAIL OF FURNACE REGISTER ALONG WEST WALL FROM NORTHEAST
- MO-1175-75 DINING ROOM (110), FIRST FLOOR, NORTH WALL FROM SOUTHWEST

- MO-1175-76 BUTLER'S PANTRY (111), FIRST FLOOR, NORTHEAST CORNER
FROM SOUTHWEST
- MO-1175-77 BUTLER'S PANTRY (111), FIRST FLOOR, NORTHWEST CORNER
FROM SOUTHEAST
- MO-1175-78 PANTRY (112), FIRST FLOOR, SOUTHWEST CORNER FROM EAST
- MO-1175-79 KITCHEN (113), FIRST FLOOR, SOUTHEAST CORNER FROM
NORTHWEST
- MO-1175-80 KITCHEN (113), FIRST FLOOR, WEST WALL FROM NORTHEAST
ENTRANCE
- MO-1175-81 KITCHEN (113), FIRST FLOOR, NORTH WALL FROM
SOUTHWEST ENTRANCE

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:
HARRY S. TRUMAN HOUSE
Harry S. Truman National Historic Site
219 North Delaware Street
Independence
Jackson County
Missouri

HABS MO-1175
HABS
MO
48-INDEP
3-

Photographs HABS MO-1175-1 through HABS MO-1175-81 were previously transmitted to Library of Congress.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Jack E. Boucher, photographer, March 1983

MO-1175-82	Center Hall (202), second floor, overview from the east entrance
MO-1175-83	Center Hall (202), second floor, east section from the northwest
MO-1175-84	Center Hall (202), second floor, detail of desk along south wall from the northwest
MO-1175-85	Center Hall (202), second floor, northwest corner from the southeast
MO-1175-86	Center Hall (202), second floor, detail of cabinet in northwest corner from the southeast
MO-1175-87	Center Hall (202), second floor, detail of cabinet on west wall from the northeast
MO-1175-88	Master Bedroom (204), second floor, east wall from the west
MO-1175-89	Master Bedroom (204), second floor, south wall from northeast corner
MO-1175-90	Master Bedroom (204), second floor, fireplace and television on south wall from center of east wall

HARRY S. TRUMAN HOUSE
HABS MO-1175
INDEX TO PHOTOGRAPHS
PAGE 10

- MO-1175-91 Master Bedroom (204), second floor, detail of fireplace mantel on south wall from the north
- MO-1175-92 Master Bedroom (204), second floor, southwest corner from the center of room
- MO-1175-93 Master Bedroom (204), second floor, north section of west wall from east wall
- MO-1175-94 Master Bedroom (204), second floor, northwest corner from southeast corner
- MO-1175-95 Master Bedroom (204), second floor, southwest corner from the northeast corner
- MO-1175-96 Truman Bedroom (205), second floor, southwest corner from northeast corner
- MO-1175-97 Truman Bedroom (205), second floor, dresser on south wall
- MO-1175-98 Truman Bedroom (205), second floor, east wall from northwest corner
- MO-1175-99 Truman Bedroom (205), second floor, north wall from southwest corner
- MO-1175-100 Northwest Bedroom (207), second floor, northeast corner from southwest corner
- MO-1175-101 Northwest Bedroom (207), second floor, northeast corner from southwest corner
- MO-1175-102 Northwest Bedroom (207), second floor, southeast corner from northwest corner
- MO-1175-103 Northwest Bedroom (207), second floor, southwest corner from the northeast
- MO-1175-104 Northwest Bedroom (207), second floor, northwest corner from the southwest
- MO-1175-105 Truman's Dressing Room (209), second floor, looking north from the south door, southeast corner
- MO-1175-106 Truman's Dressing Room (209), second floor, looking north from the south door, southeast corner

HARRY S. TRUMAN HOUSE

HABS MO-1175
INDEX TO PHOTOGRAPHS
PAGE 11

- MO-1175-107 Truman's Dressing Room (209), second floor, looking southeast from the northeast corner
- MO-1175-108 Truman's Dressing Room (209), second floor, looking south from the north wall
- MO-1175-109 North Closet (209-B) and Passage between Truman Dressing Room (209) and the Storage Room (213), second floor, from the south wall looking northeast
- MO-1175-110 Truman's Dressing Room Closet (209-C), second floor, southeast corner from the northwest
- MO-1175-111 East Bedroom (210), second floor, looking south from the north wall
- MO-1175-112 East Bedroom (210), second floor, dresser on east wall
- MO-1175-113 East Bedroom (210), second floor, looking north from south wall
- MO-1175-114 East Bedroom (210), second floor, dresser on south side of west wall
- MO-1175-115 Bathroom (211), second floor, east wall from southwest entrance
- MO-1175-116 Storage Room (213), second floor, east and south walls from northwest entrance
- MO-1175-117 Storage Room (213), second floor, west wall from the east
- MO-1175-118 New Attic, Lower Level (302), third floor, northeast corner from the southwest
- MO-1175-119 New Attic, Lower Level (302), third floor, southeast corner from the west
- MO-1175-120 New Attic, Lower Level (302), third floor, southeast corner from the northwest
- MO-1175-121 New Attic, Lower Level (302), third floor, northwest corner from the southeast
- MO-1175-122 New Attic, Lower Level (302), third floor, detail of northeast corner from the southwest
- MO-1175-123 New Attic, Upper Level (303), third floor, east wall and southeast corner

HARRY S. TRUMAN HOUSE

HABS MO-1175
INDEX TO PHOTOGRAPHS
PAGE 12

MO-1175-124 New Attic, Upper Level (303), third floor, southwest corner from
the east

INDEX TO COLOR TRANSPARENCIES

Jack E. Boucher, photographer, March 1983

MO-1175-125 (CT) West elevation from east side of Delaware Street. Duplicate color
view of HABS MO-1175-2