

Wilkinson House  
(Kingsway Center Commercial Area)  
1347 Euclid Avenue  
St. Louis  
St. Louis County  
Missouri

HABS No. MO-60-N

HABS  
MO,  
96-SALU,  
133-N-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

Historic American Buildings Survey  
National Park Service  
Rocky Mountain Regional Office  
Department of the Interior  
P.O. Box 25287  
Denver, Colorado 80225

**NATIONAL PARK SERVICE  
 ROCKY MOUNTAIN REGION**

**ARCHITECTURAL DATA FORM**

<b>STATE</b> MISSOURI	<b>COUNTY</b>	<b>TOWN OR VICINITY</b> CITY OF SAINT LOUIS
--------------------------	---------------	--

<b>HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME)</b> Wilkinson House (Permits)	<b>EABS NO.</b> MO-60-N
--	----------------------------

**SECONDARY OR COMMON NAMES OF STRUCTURE**

**COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)**  
 1347 Euclid Avenue

<b>DATE OF CONSTRUCTION (INCLUDE SOURCE)</b> 1892 (Permits)	<b>ARCHITECT(S) (INCLUDE SOURCE)</b> L. Silva - owner (Permits)
--	--

**SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL. INCLUDE ORIGINAL USE OF STRUCTURE)**  
 The Kingsway Center Area is locally significant for its architectural significance as an important representative illustration of neighborhood development and urban vernacular building traditions in late 19th-century St. Louis. The Wilkinson House is one of the bldgs. in the area that contributes to a potential historic district. Original Use: single-family residence.

**STYLE (IF APPROPRIATE)** Queen Anne

**MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS)** Cut stone foundation. Full basement w/concrete floor. Brick walls. Masonry building frame. Galvanized gutters & downspouts. Gable roof, asphalt shingle. Hardwood floors. Plaster walls & ceilings. Cast iron & galvanized plumbing. Gas forced warm air. Incandescent lighting. 40 gallon gas water heater.

**SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)**  
 Floor Plan Attached.

**EXTERIOR FEATURES OF NOTE** Arched bays with roll moulding outlining & connecting bays on both floors. Wood panelled entry way. Wood window frames with metal framed lights. Masonry sills with ovolo mouldings. Dormer with round overhang. Pilaster divide lights into three. Slate shingles on gable ends and rounded stone porch pillars.

**INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)**  
 Floor Plan Attached.



**MAJOR ALTERATIONS AND ADDITIONS WITH DATES**  
 No records found.

**PRESENT CONDITION AND USE**  
 Good condition. Single-family residence.

**OTHER INFORMATION AS APPROPRIATE**  
 Available records show that L. Silva initially owned this parcel and constructed the building. Mr. Wilkinson purchased the building and was the first occupant.



**SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)**  
 Building Division of the City of St. Louis. Records of the City Assessor. Appraisal report-Real Estate Analysts, Ltd. Report of Cultural Resource Assessment-Archaeological Survey, University of Missouri-St. Louis. Gould's City Directory/Blue Book, 1893, 1896, 1897, and 1898. Notification from the Keeper of the National Register and the Missouri Historic Preservation Program.

<b>COMPILER, AFFILIATION</b> Claude Louishomme, Project Manager	<b>DATE</b> July 18 1986
--	-----------------------------





WILKINSON HOUSE  
1347 Euclid Ave  
Saint Louis, MO  
August 5, 1986

1ST FLOOR



WILKINSON HOUSE  
1347 Euclid Ave  
Saint Louis, MO  
August 5, 1986

2ND FLOOR



WILKINSON HOUSE  
1347 Euclid Ave  
Saint Louis, MO  
August 5, 1986

ATTIC