

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MO
96-SALU,
134M-

MALLINCKRODT CHEMICAL WORKS, Building No. 705
(Mallinckrodt Inc.)

HABS No. MO-1929-M

Destrehan Street between Hall and Wharf Street
attached to Buildings 704 and 706
St. Louis, Missouri

Bruce A. Harms (LBA), Photographer, September 1996

- MO-1929-M-1 VIEW OF BUILDING 705 SHOWING THE NORTH SIDE, FACING SOUTH.
- MO-1929-M-2 VIEW OF BUILDING 705 WITH BUILDING 704 AT LEFT, SHOWING THE EAST SIDE, FACING WEST.
- MO-1929-M-3 VIEW OF BUILDING 705 SHOWING THE SOUTH SIDE, FACING NORTH.
- MO-1929-M-4 VIEW OF BUILDING 705 SHOWING THE SOUTH AND WEST SIDE, FACING NORTHEAST.
- MO-1929-M-5 INTERIOR VIEW OF BUILDING 705, FIRST FLOOR, SHOWING ENTRY TO STAIR/HALLWAY AT LEFT, FORMER MAINTENANCE SHOP AT CENTER AND WAREHOUSE AT FOREGROUND, FACING NORTHEAST.
- MO-1929-M-6 INTERIOR VIEW OF BUILDING 705, FIRST FLOOR WAREHOUSE, FACING SOUTHWEST.
- MO-1929-M-7 INTERIOR VIEW OF BUILDING 705, FIRST FLOOR STAIR/HALLWAY, FACING SOUTHWEST.
- MO-1929-M-8 INTERIOR VIEW OF BUILDING 705, SECOND FLOOR, SHOWING STRUCTURAL DETAILS, FACING SOUTH. CORRUGATED METAL FLOORING IS ROOF OF FIRST FLOOR. THE ORIGINAL METAL FLOORING HAS BEEN REMOVED, LEAVING A LARGE OPEN AREA.
- MO-1929-M-9 INTERIOR DETAIL OF BUILDING 705, SECOND FLOOR, SHOWING MECHANICAL PIPEWORK THROUGH FLOORS, FACING NORTH.

MALLINCKRODT CHEMICAL WORKS
(Mallinckrodt Inc.)
HABS No. MO-1929-M
INDEX TO PHOTOGRAPHS
(Page 2)

- MO-1929-M-10 INTERIOR VIEW OF CATWALK FROM BUILDING 705 TO BUILDING 117, SHOWING CONSTRUCTION DETAILS, FACING NORTH.
- MO-1929-M-11 INTERIOR VIEW OF BUILDING 705, THIRD FLOOR, ROOF OF ELECTRIC SUBSTATION AREA IN THE NORTHEAST CORNER, FACING NORTHEAST.
- MO-1929-M-12 DETAIL VIEW OF MECHANICAL PIPEWORK SHUTOFF VALVES, BUILDING 705, THIRD FLOOR, FACING NORTH.
- MO-1929-M-13 INTERIOR VIEW OF BUILDING 705, FOURTH FLOOR, SHOWING WOOD HATCH TO ROOF, FACING SOUTH.
- MO-1929-M-14 INTERIOR VIEW OF BUILDING 705, FOURTH FLOOR, SHOWING OPEN AREA IN NORTHEAST CORNER, AND LAMP DETAILS, FACING NORTHEAST.
- MO-1929-M-15 INTERIOR DETAIL VIEW OF BUILDING 705, FOURTH FLOOR LOUVERED VENT WITH METAL SHUTTERS THE WEST WALL, FACING WEST.
- MO-1929-M-16 INTERIOR DETAIL VIEW OF BUILDING 705 STAIRWELL TO FOURTH FLOOR, FACING WEST.

*FOR SITE PLANS SEE MO-1929 FIELD NOTES