

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
MONT
41-HAM,
2A-

Rocky Mountain Laboratories, Building 1
903 South 4th Street, north front
Hamilton
Ravalli County
Montana

HABS No. MT-101-A

Bruce D. Judd, FAIA, Photographer (MT-101-A-4-6, 8)
John Ash, AIA, Photographer (MT-101-A-1-3, 7, 9-17)
Robert Evans, Photographer (MT-101-A21-A23)

May 22-29, 1996

- MT-101-A-1 EXTERIOR CONTEXT VIEW WITH NORTH END OF BUILDING 1,
LOOKING WEST-SOUTHWEST DOWN FOURTH STREET.
- MT-101-A-2 EXTERIOR OBLIQUE CONTEXT VIEW WITH NORTH END OF
BUILDING 1, LOOKING WEST-SOUTHWEST.
- MT-101-A-3 EXTERIOR OBLIQUE VIEW OF BUILDING 1, LOOKING NORTH-
NORTHWEST.
- MT-101-A-4 EAST ELEVATION VIEW OF BUILDING 1, LOOKING WEST-
NORTHWEST.
- MT-101-A-5 EXTERIOR DETAIL VIEW OF CENTRAL PORTION OF BUILDING
1, LOOKING NORTH-NORTHWEST.
- MT-101-A-6 EXTERIOR DETAIL OF EAST ENTRYWAY OF BUILDING 1,
LOOKING WEST-SOUTHWEST.
- MT-101-A-7 EXTERIOR OBLIQUE VIEW OF BUILDING 1, LOOKING WEST-
SOUTHWEST.
- MT-101-A-8 EXTERIOR ELEVATION VIEW OF NORTH END OF BUILDING 1,
LOOKING SOUTH-SOUTHWEST.
- MT-101-A-9 EXTERIOR VIEW OF TICK MOAT SURROUNDING BUILDING 1,
LOOKING SOUTHWEST.
- MT-101-A-10 INTERIOR VIEW OF BUILDING 1 ENTRY, LOOKING
NORTHWEST.

ROCKY MOUNTAIN LABORATORIES,
BUILDING 1
HABS NO. MT-101-A (page 2)
INDEX TO PHOTOGRAPHS

- MT-101-A-11 INTERIOR VIEW OF BUILDING 1, MAIN STAIRWAY, LOOKING
SOUTHWEST.
- MT-101-A-12 INTERIOR VIEW OF BUILDING 1, MAIN STAIRWAY FROM
ENTRANCE LOBBY, LOOKING SOUTHEAST.
- MT-101-A-13 INTERIOR VIEW OF BUILDING 1, SECOND FLOOR LOBBY,
LOOKING EAST TOWARD MAIN STAIR.
- MT-101-A-14 INTERIOR AXIAL VIEW OF BUILDING 1, SECOND FLOOR
CORRIDOR, LOOKING SOUTH-SOUTHEAST.
- MT-101-A-15 INTERIOR VIEW OF BUILDING 1 ELEVATOR, LOOKING
SOUTHWEST.
- MT-101-A-16 INTERIOR DETAIL VIEW OF BUILDING 1, ROOM 200 WINDOW,
LOOKING EAST.
- MT-101-A-17 INTERIOR VIEW OF BUILDING 1, THIRD FLOOR LIBRARY,
LOOKING NORTH-NORTHEAST.

*PHOTOGRAPHS MT-101-A-18 THROUGH MT-101-A-20 ARE PHOTOCOPIES OF
HISTORIC VIEWS. 8" X 10" PHOTOS AND NEGATIVES WERE MADE FROM
ENLARGEMENTS PROVIDED BY ROCKY MOUNTAIN LABORATORIES. ORIGINAL
PHOTOS AND NEGATIVES ARE ALSO LOCATED AT ROCKY MOUNTAIN
LABORATORIES AND NEGATIVE NUMBERS ARE NOTED IN PARENTHESES. THE
PHOTOGRAPHER IS ASSUMED UNKNOWN UNLESS NOTED.*

- MT-101-A-18 Photocopy of photograph (RML Negative #467). August 9, 1927.
CONSTRUCTION VIEW OF BUILDING 1 SHOWING CONCRETE
FORMS FOR THE FIRST, SECOND AND THIRD FLOORS.
- MT-101-A-19 Photocopy of photograph (RML Negative #455). May 5, 1928.
FRONT VIEW OF LABORATORY BUILDING 1.
- MT-101-A-20 Photocopy of photograph (RML Negative #456) Signed: Johnsons',
November 10, 1931.
VIEW OF BUILDING 1 LOOKING NORTHEAST.

;

ROCKY MOUNTAIN LABORATORIES,
BUILDING 1
HABS NO. MT-101-A (page 3)
INDEX TO PHOTOGRAPHS

Photographs MT-101-A-21 through MT-101-A-23 are 8x10 enlargements of 4x5 negatives. The original drawings are located at Rocky Mountain Laboratories. The photographer was Robert Evans.

- | | |
|-------------|---|
| MT-101-A-21 | Photocopy of construction drawing Building 1, November 5, 1938
(Drawing Number 1-1-1). |
| MT-101-A-22 | Photocopy of construction drawing Building 1, November 5, 1938
(Drawing Number 1-1-100). |
| MT-101-A-23 | Photocopy of construction drawing Building 1, November 5, 1938
(Drawing Number 1-1-200). |