

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
MONT
47-MEL.V,
1K-

William and Lucina Bowe Ranch,
Post-and-Beam Garage
135 feet southwest of House
Melrose Vicinity
Silver Bow County
Montana

HABS No. MT-104-K

Documentation: 4 exterior photographs (1997)
1 interior photograph
2 data pages

Kristi Hager, Photographer, June 1997

MT-104-K-1 GARAGE. FRONT (NORTH) FACADE. VIEW TO SOUTH.

MT-104-K-2 GARAGE. EAST SIDE. VIEW TO WEST.

MT-104-K-3 GARAGE. REAR (SOUTH). VIEW TO NORTH.

MT-104-K-4 GARAGE. WEST SIDE. VIEW TO EAST.

MT-104-K-5 GARAGE. DETAIL OF ROOF SHOWING LOG RAFTERS AND POLE
BRACING,