

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
NH,
10-CLAR,
1-

David Dexter House (Dexter-Fitchburg House)
Claremont
Sullivan County
New Hampshire

HABS No. NH-195

Documentation: 4 exterior photos (1975)
23 interior photos (1975)
3 photocopies of 1975 drawings
3 data pages (1982)

Lewis G. Smith, photographer 1975

- NH-195-1 South (front) elevation, a general view
- NH-195-2 View of east (side) elevation with rear addition
- NH-195-3 View of west (side) and north (rear) elevations,
with rear addition
- NH-195-4 Rear view of house and addition
- NH-195-5 Parlour (Room 3) on front west side of first floor, looking
north. Note Federal mantelpiece and denticulated cornice
- NH-195-6 Parlour (Room 3) on front west side of first floor, looking
northeast. Door on the left was a closet. Door on the right
led to the hallway
- NH-195-7 Parlour (Room 3) on front west side of first floor, looking
south. Note panels above windows
- NH-195-8 Parlour (Room 3) on front west side of first floor, looking
west
- NH-195-9 Dining Room (Room 1) on front east side of first floor, looking north. N
doorway trim and "H-L" hinges on paneled door
- NH-195-10 Rear room (Room 4) on west side of first floor. Fireplace
faces south and window faces west
- NH-195-11 Rear room (Room 4) on west side of first floor, looking southeast
- NH-195-12 Rear room (Room 4) on west side of first floor, looking northwest

(continued to page 2)

- NH-195-13 Main entrance door looking south. Note wide size with transom light and hand-wrought heart-shaped hinges
- NH-195-14 Door with hand-wrought heart-shaped hinge, located between kitchen and Dining Room (Room 1) on east side of first floor
- NH-195-15 Indian shuttered window, located in the dining room on front east side of first floor, looking east
- NH-195-16 Kitchen hearth in rear room (Room 6) on east side of first floor, looking south. Narrow door on the right was a cupboard
- NH-195-17 Open-string stairway, first floor hallway (Room 2), looking east
- NH-195-18 Detail of first floor stairway
- NH-195-19 Front second floor bedroom (Room 7) on east side of house, looking north. Note "H-L" hinges on paneled doors
- NH-195-20 Front second floor bedroom (Room 9) on west side of house, looking north
- NH-195-21 Rear second floor bedroom (Room 10) on west side of house, looking south. Note "H-L" hinges on closet doors
- NH-195-22 Second floor hall (Room 8) and stairway landing, center of house
- NH-195-23 Stairway to third floor
- NH-195-24 Third floor hall looking south and detail of stairway
- NH-195-25 Detail view of chimney and framing system, looking east
- NH-195-26 Detail view of chimney and framing system, looking west
- NH-195-27 Summer kitchen and Dutch oven in rear addition, facing north

Photocopies

From drawings by T. West, Summer 1975. Rear addition plans not included.

- NH-195-28 First floor plan
- NH-195-29 Second floor plan
- NH-195-30 Third floor plan