

HISTORIC AMERICAN BUILDINGS SURVEY  
INDEX TO PHOTOGRAPHS

HABS  
NH  
8-NORT,  
1A-

BATCHELDER-EDGERLY FARMSTEAD, BARN  
NH Route 4, southwest side, southeast corner of NH Route 43  
Northwood  
Rockingham County  
New Hampshire

HABS No. NH-237-A

Photographer: Charley Freiberg, August 1998, for Preservation Company, 5 Hobbs Road,  
Kensington, NH 03801

- NH-237-A-1 Intersection of US Route 4 and NH Route 143, showing farm house on left, barn at right. Looking east.
- NH-237-A-2 US Route 4, barn at left. Looking northwest.
- NH-237-A-3 Façade and northwest elevation. Looking south.
- NH-237-A-4 Façade and southeast elevation. Looking southwest.
- NH-237-A-5 Façade and southeast elevation. Looking west.
- NH-237-A-6 Façade. Looking southwest.
- NH-237-A-7 Southeast elevation. Looking northwest.
- NH-237-A-8 Northwest elevation. Looking southeast.
- NH-237-A-9 Rear and southeast elevations. Looking north.
- NH-237-A-10 Rear elevation. Looking northeast.
- NH-237-A-11 Interior. Looking northeast toward front door.
- NH-237-A-12 Interior. Looking southwest toward rear.
- NH-237-A-13 Interior. Looking southwest toward rear.
- NH-237-A-14 Interior. Looking northeast.
- NH-237-A-15 Interior. Stanchions and box stall. Looking north.

BATCHELDER-EDGERLY FARMSTEAD, BARN  
HABS No. NH-237-A  
Key to Photographs  
(Page 2)



