

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
NJ
10-55TA.V)
1-

John S. Britton House
East side of New Jersey Route 31
at Old Clinton Road
Stanton Station Vicinity
Hunterdon County
New Jersey


HABS No. NJ-983

Photographer: Rob Tucher



March 1994

- NJ-983 -1 GENERAL VIEW EAST-NORTHEAST
- NJ-983 -2 GENERAL VIEW WEST-NORTHWEST
- NJ-983 -3 VIEW NORTH, SOUTH FACADE
- NJ-983 -4 VIEW SOUTHEAST, WEST ELEVATION
- NJ-983 -5 VIEW SOUTH, NORTH ELEVATION
- NJ-983 -6 VIEW SOUTHWEST, EAST AND NORTH ELEVATIONS
- NJ-983 -7 EAST SECTION, FIRST FLOOR, VIEW SOUTHEAST, LIVING ROOM
- NJ-983 -8 WEST SECTION, FIRST FLOOR, VIEW NORTHWEST, DINING ROOM
- NJ-983 -9 EAST SECTION, SECOND FLOOR, VIEW SOUTHEAST, EAST AND WEST BEDROOMS
- NJ-983 -10 WEST SECTION, SECOND FLOOR, VIEW WEST, NORTHWEST BEDROOM
- NJ-983 -11 BARN, VIEW NORTHWEST, SOUTH AND EAST ELEVATIONS

KEY TO PHOTOGRAPHS
JOHN S. BRITTON HOUSE
HABS No. NJ-983 (Page 2)





KEY TO PHOTOGRAPHS
JOHN S. BRITTON HOUSE
HABS No. NJ- 983 (Page 3)



NORTH

First Floor Plan
Not to Scale
Prepared By: Jill Cremer

KEY TO PHOTOGRAPHS
JOHN S. BRITTON HOUSE
HABS No. NJ- 983 (Page 4)



NORTH

Second Floor Plan
Not to Scale
Prepared By: Jill Cremer