

HABS  
NM  
16-EROPD.V,  
1-

## HISTORIC AMERICAN BUILDINGS SURVEY

### INDEX TO PHOTOGRAPHS

BEE BURROW  
Chaco Outliers  
Seven Lakes Wash  
Crownpoint vicinity  
McKinley County  
New Mexico

HABS No. NM-180

Robert Lyon, Photographer          June 1994

- NM-180-1      PRIMITIVE WIND BREAK AT HIGHEST POINT ON RIDGE,  
APPROXIMATELY ¼ MILE NORTHEAST OF SITE, VIEW TOWARDS  
NORTH
- NM-180-2      CHECK DAM, APPROXIMATELY 300 YARDS NORTHEAST OF SITE,  
VIEW TOWARDS NORTH
- NM-180-3      DISTANT VIEW FROM NORTHWEST
- NM-180-4      DISTANT VIEW FROM SOUTH
- NM-180-5      DISTANT VIEW FROM SOUTHEAST
- NM-180-6      DISTANT VIEW FROM NORTH
- NM-180-7      SUGGESTED LOCATION OF CHACO ROAD, VIEW TOWARDS  
NORTH
- NM-180-8      OVERALL VIEW OF SITE, NORTH WALL AT LEFT, VIEW TOWARDS  
SOUTHEAST
- NM-180-9      OVERALL VIEW OF SITE, NORTH WALL AT LEFT AND CENTER,  
VIEW TOWARDS NORTHEAST
- NM-180-10     EASTERNMOST ELEVATION IN NORTH WALL, VIEW TOWARDS  
SOUTH
- NM-180-11     HIGHEST ELEVATION IN NORTH WALL, VIEW TOWARDS SOUTH

- NM-180-12 NEXT SECTION OF NORTH WALL, VIEW TOWARDS SOUTH
- NM-180-13 WESTERNMOST ELEVATION IN NORTH WALL, VIEW TOWARDS SOUTH
- NM-180-14 WALL EXTENSION AT SOUTHEAST CORNER OF SITE, VIEW TOWARDS EAST
- NM-180-15 INTERIOR OF SITE, SOUTH SIDE OF NORTH WALL AT RIGHT, VIEW TOWARDS NORTHWEST
- NM-180-16 SOUTHWEST CORNER OF HIGHEST NORTH WALL ELEVATION SHOWING ROCK PROTRUDING FOR CONNECTION TO INTERIOR WALL, VIEW TOWARDS NORTHWEST
- NM-180-17 NORTH FACE OF INTERIOR ELEVATION WHOWING REMAINS OF INTERIOR WALL VIEW TOWARDS EAST
- NM-180-18 DETAIL OF WALL CONSTRUCTION, EAST EDGE OF HIGHEST ELEVATION NORTH WALL VIEW TOWARDS WEST
- NM-180-19 KIVA, VIEW TOWARDS NORTHWEST
- NM-180-20 KIVA, VIEW TOWARDS NORTH
- NM-180-21 KIVA WALL CONSTRUCTION DETAIL, BASE OF THE WALL EXCAVATED BY POTHUNTERS, VIEW TOWARDS WEST
- NM-180-22 FIRE PIT OUTHEST OF KIVA ENTRANCE, POTSHARDS ON ROCK AT TOP, VIEW TOWARDS SOUTHEAST
- NM-180-23 SNAKE PETROGLYPH ON ROCK FACE WEST OF SITE, VIEW TOWARDS WEST
- NM-180-24 THUNDERBIRD PETROGLYPH AT UPPER LEFT, ON CLIFF FACE FURTHER WEST OF SITE, PETROGLYPHS AT RIGHT OF UNDETERMINED ORIGIN, VIEW TOWARDS NORTHEAST
- NM-180-25 SPIRAL BIRD PETROGLYPH AT LEFT CENTER ON CLIFF FACE FURTHER WEST OF SITE, HOLES FOR ROOF BEAMS AT CENTER, VIEW TOWARDS SOUTHEAST