

HISTORIC AMERICAN ENGINEERING RECORD

HAER
NEV,
1-FALL,
1E-

Index to Photographs

Truckee-Carson Irrigation District
Facility District, Car Repair Shop
6th and Taylor Streets
Fallon
Churchill County
Nevada

HAER No. NV-6-E

NOTE: Photographs were taken by Don Westphal, photographer, August 1984

- NV-6-E-1 VIEW OF FRONT SIDE OF CAR REPAIR SHOP, LOOKING NORTH
- NV-6-E-2 VIEW OF WEST SIDE OF CAR REPAIR SHOP
- NV-6-E-3 VIEW OF SOUTH SIDE OF CAR REPAIR SHOP (EAST END)
- NV-6-E-4 VIEW OF SOUTH SIDE OF CAR REPAIR SHOP (MIDDLE SECTION)
- NV-6-E-5 VIEW OF SOUTH SIDE OF CAR REPAIR SHOP (WEST END)
- NV-6-E-6 VIEW OF EAST SIDE OF CAR REPAIR SHOP (2-1/2" x 3" negative)
- NV-6-E-7 INTERIOR VIEW OF CAR REPAIR SHOP, LOOKING WEST
(2-1/2" x 3" negative)