

HISTORIC AMERICAN BUILDINGS SURVEY

HABS
NEV
12-MERC.V,
3A-

INDEX TO PHOTOGRAPHS

Nevada Test Site, Environmental Protection Agency Farm, HABS No. NV-28-A
Lab Building (Building No. 15-06)
Area 15, Yucca Flat, 10-2 Road near Circle Road
Mercury Vicinity
Nye County
Nevada

Rick Smith, RSL Photographic Services Photographer September 1997

- NV-28-A-1 VIEW OF EPA FARM LAB BUILDING 15-06, FACING SOUTH.
- NV-28-A-2 OBLIQUE VIEW OF EPA FARM LAB BUILDING 15-06 (WITH SLAUGHTER ADDITION AT FAR LEFT), FACING SOUTHWEST.
- NV-28-A-3 VIEW OF EPA FARM LAB BUILDING 15-06 (WITH SLIDING DOORS OPEN TO SLAUGHTER ADDITION) AND SIOUX SILO, FACING NORTH-NORTHWEST.
- NV-28-A-4 OBLIQUE VIEW OF EPA FARM LAB BUILDING 15-06 (WITH SLIDING DOOR OPEN TO MILKING AREA), SIOUX SILO AND SLAUGHTER ADDITION, FACING NORTHEAST.
- NV-28-A-5 VIEW OF INTERIOR, EPA FARM LAB BUILDING 15-06 SLAUGHTER ADDITION (FEATURING COLD SLAUGHTER AREA), FACING NORTH-NORTHEAST.
- NV-28-A-6 VIEW OF INTERIOR, EPA FARM LAB BUILDING 15-06 MILKING AREA, FACING NORTHWEST.
- NV-28-A-7 VIEW OF INTERIOR, EPA FARM LAB BUILDING 15-06 MILK ROOM, FACING WEST.

Note: For additional written historical and descriptive information, please see the main entry for the Nevada Test Site, Environmental Protection Agency Farm, HABS No. NV-28.