

HABS
NY,
60-SCAR
3-

HISTORIC AMERICAN BUILDINGS SURVEY



INDEX TO PHOTOGRAPHS

SCARSDALE RAILROAD STATION
East Parkway
Scarsdale
Westchester Co.
New York


HABS No. NY-6292

Photographer: (Views 1-16) Stephen L. Senigo May, 1988

- NY-6292-1 VIEW OF SOUTH FACADE OF OUTBOUND STATION
- NY-6292-2 VIEW WEST ACROSS EAST PARKWAY
- NY-6292-3 VIEW WEST, OF OUTBOUND STATION
- NY-6292-4 VIEW SOUTHWEST ALONG EAST PARKWAY
- NY-6292-5 VIEW SOUTH ALONG EAST PARKWAY
- NY-6292-6 VIEW OF SHELTER OF OUTBOUND STATION
- NY-6292-7 VIEW OF NORTH FACADE OF BRIDGE
- NY-6292-8 VIEW OF INBOUND STATION FROM BRIDGE
- NY-6292-9 VIEW OF SOUTH FACADE OF BRIDGE
- NY-6292-10 VIEW OF INBOUND STATION, EAST FACADE
- NY-6292-11 VIEW OF INBOUND STATION FROM NORTHWEST
- NY-6292-12 VIEW OF INBOUND STATION FROM SOUTHWEST
- NY-6292-13 VIEW OF INBOUND STATION FROM SOUTH
- NY-6292-14 VIEW NORTH FROM INBOUND TRACKS
- NY-6292-15 VIEW (INTERIOR) TOWARD ENTRANCE, INBOUND STATION
- NY-6292-16 VIEW (INTERIOR) TOWARD TRACKS, INBOUND STATION



- 11 ▲
- 12 ▼
- 13 ▲
- 14 ▲
- 10 ▲
- 6 ▲
- 5 ▼
- 4 ▲
- 3 ▲
- 2 ▼
- 1 ▲



M METRO-NORTH COMMUTER RAILROAD
 MID-HARLEM STATION IMPROVEMENTS
 CONTRACT NO. 7388
 SCARSDALE STATION HOUSE
VONDER CONTRACTING COMPANY, INC.
 Goodkind & O'Dea, Inc.
 CONSULTING ENGINEERS