

HABS
OHIO
40-WELLS,
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS



WELLSTON COAL COMPANY STORE
4 West Broadway
Wellston, Jackson County, Ohio

HABS No. OH-2356


Photographer (All Photographs) Barry Peper May, 1989

- OH -2356 -1- View of north (main) and east side facades looking southwest.
- OH-2356 -2- View of north (main) and west side facades looking southeast.
- OH-2356 -3- View of east and south side facades looking northwest.
- OH-2356 -4- View of south and part of west side facades looking northeast.
- OH-2356 -5- Streetscape view of complex looking east along south side of Broadway.
- OH-2356 -6- View of upper story detail on east side facade.
- OH-2356 -7- View of rear portion of east side facade on original part of building.
- OH-2356 -8- Interior view of wooden columns and beams at rear addition, first floor.
- OH-2356 -9- Overall interior view of rear addition looking west, first floor.
- OH-2356 -10- Interior view of rear addition looking north, first floor.
- OH-2356 -11- Interior view of addition looking northeast, first floor.
- OH-2356 -12- Overall view of second floor interior of original building looking north.
- OH-2356 -13- View of typical interior window surrounds found at second floor of original building.
- OH-2356 -14- Overall view of second floor interior looking west in addition.

Exterior View of Photographs



View of Photographs
First Floor



View of Photographs
Second Floor



north

Not to Scale

