



Index to Photographs  
4825 Guernsey Street (House)  
HABS No. OH-2383 (Page 2)

OH 2383-18            Inside view of front door and pocket doors.

OH 2383-19            View of front room - looking east.

OH 2383-20            View of front room - looking southwest.

OH 2383-21            View of front room - looking northwest.

OH 2383-22            View of parlor - looking east.

OH 2383-23            View of dining room - looking west.

OH 2383-24            View of dining room pocket doors and closet.

OH 2383-25            View of dining room - looking southeast.

OH 2383-26            View of dining room - looking southwest.

OH 2383-27            View of pantry - looking east.

OH 2383-28            View of kitchen - looking west.

OH 2383-29            Stairway - looking down to the northwest.

OH 2383-30            Second floor hallway - looking southwest.

OH 2383-31            Bathroom - looking west.

OH 2383-32            Front bedroom - looking east.

OH 2383-33            Dressing room - looking northeast.

OH 2383-34            Twin closet doors - looking west.

OH 2383-35            Attic room - looking east.

OH 2383-36            Attic room - looking west.


OH 2383-37            Side attic room - looking south.

OH 2383-38            Front attic room showing eyebrow window -  
looking northeast.

OH 2383-39            Front attic room showing eyebrow window and  
inside window opening to outside round  
window - looking northeast.


4825 GUERNSEY STREET (House)  
HABS No. OH-2383  
INDEX TO PHOTOGRAPHS  
(Page 3)

NORTH →



FIRST FLOOR


**NORTH** →



SECOND FLOOR

4825 GUERNSEY STREET (House)  
HABS No. OH-2383  
INDEX TO PHOTOGRAPHS  
(Page 5)

**NORTH** →



ATTIC FLOOR