

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS


HABS No. OH-2421

HABS
OHIO
56-RINMI.V,
1-

Walter Ring House *Wayne National Forest*
North Side of Township Road 575 at Little Muskingum River
Rinard Mills Vicinity
Monroe County, Ohio

Jeff Bates, Photographer, November 1996

- OH-2421-1 CONTEXT LOOKING NORTHEAST
- OH-2421-2 CONTEXT LOOKING WEST
- OH-2421-3 NORTHWEST FRONT CORNER
- OH-2421-4 WEST FRONT ELEVATION
- OH-2421-5 SOUTHEAST REAR CORNER
- OH-2421-6 DETAIL OF NORTH WALL
- OH-2421-7 INTERIOR VIEW OF NORTH ROOM FIREPLACE LOOKING
NORTHWEST
- OH-2421-8 INTERIOR DETAIL OF SOUTH ROOM WALL LOOKING
NORTHWEST
- OH-2421-9 DETAIL OF FRONT DOOR ON WEST WALL
- OH-2421-10 DETAIL OF DOORWAY ON SOUTH WALL OF HALLWAY
- OH-2421-11 EXTERIOR DETAIL OF FRONT DOOR ON WEST WALL
- OH-2421-12 PHOTOCOPY OF PHOTOGRAPH SHOWING CONTEXT VIEW
LOOKING NORTH DATED CIRCA 1915. PRINT SHOWS THE
DWELLING IN THE LOWER RIGHT CORNER. (ORIGINAL PRINT
IN POSSESSION OF USDA FOREST SERVICE, ATHENS, OHIO,
DISTRICT OFFICE)
- OH-2421-13 PHOTOCOPY OF PHOTOGRAPH SHOWING FRONT AND SIDE
VIEWS DATED CIRCA 1970. (ORIGINAL PRINT IN POSSESSION
OF USDA FOREST SERVICE, ATHENS, OHIO, DISTRICT OFFICE)



FIRST FLOOR VIEWS