

HABS
OKLA,
55-OKLA,
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Municipal Building
200 N. Walker
Oklahoma City
Oklahoma County
Oklahoma

HABS No. OK-40

Bill Peavler, AIA, photographer, July 25, 1981

- OK-40-1 East elevation
- OK-40-2 North elevation
- OK-40-3 West elevation
- OK-40-4 West elevation, from southwest
- OK-40-5 South elevation
- OK-40-6 Interior, ceiling, walls, columns, and lighting fixtures in lobby
- OK-40-7 Interior, pilaster capital, probably in corridor
- OK-40-8 Interior, narrow lobby, showing ornate grillwork
- OK-40-9 Interior, lintel above council chamber door
- OK-40-10 Light fixture in council chamber