

HISTORIC AMERICAN BUILDINGS SURVEY
INDEX TO PHOTOGRAPHS

HABS
ORE
9-BEND,
1-

AMERICAN RAILWAY EXPRESS COMPANY
FREIGHT BUILDING
1060 N.E. Division Street
(At the Foot of Kearney Street)
Bend
Deschutes County
Oregon

HABS No. OR-168

James Norman, Photographer February 1999
Note: 8 x 10 images were enlarged from 4 x 5 negatives

- OR-168-1 GENERAL CONTEXT VIEW OF EXPRESS BUILDING,
LOOKING NORTHWEST WITH RAILROAD TRACKS IN
FOREGROUND
- OR-168-2 GENERAL CONTEXT VIEW OF EXPRESS BUILDING,
LOOKING NORTHEAST, WITH DIVISION STREET IN
FOREGROUND, SHOWING RELATIONSHIP TO THE BEND
DEPOT
- OR-168-3 PERSPECTIVE VIEW OF EXPRESS BUILDING LOOKING
NORTHEAST, WITH DIVISION STREET IN FOREGROUND
- OR-168-4 PERSPECTIVE VIEW OF EXPRESS BUILDING LOOKING
SOUTHEAST
- OR-168-5 PERSPECTIVE VIEW OF EXPRESS BUILDING, LOOKING
SOUTHWEST, WITH RAILROAD TRACKS IN
FOREGROUND
- OR-168-6 NORTH ELEVATION OF EXPRESS BUILDING, VIEW
LOOKING SOUTH
- OR-168-7 EAST ELEVATION OF EXPRESS BUILDING, VIEW
LOOKING WEST
- OR-168-8 SOUTH ELEVATION OF EXPRESS BUILDING, VIEW
LOOKING NORTH

**AMERICAN RAILWAY EXPRESS COMPANY BUILDING
HABS No. OR-168
INDEX TO PHOTOGRAPHS
(Page 2)**

OR-168-9 WEST ELEVATION OF EXPRESS BUILDING, VIEW LOOKING
EAST

Orrin Russie, Photographer February 1999
Note: 8 x 10 images were enlarged from 4 x 5 negatives

OR-168-10 EXTERIOR DETAIL VIEW OF EAST ELEVATION

OR-168-11 EXTERIOR DETAIL VIEW OF NORTHEAST CORNER,
SHOWING STUCCO FINISH AND WOODWORK DETAILS

OR-168-12 EXTERIOR DETAIL VIEW OF ROOF STRUCTURE AT EAVE,
SHOWING EXPOSED RAFTER TAILS, SKIP SHEATHING
AND GUTTER

James Norman, Photographer February 1999
Note: 8 x 10 images were enlarged from 4 x 5 negatives

OR-168-13 INTERIOR VIEW: NORTHEAST CORNER OF EXPRESS
BUILDING, LOOKING EAST

OR-168-14 INTERIOR VIEW: NORTHEAST CORNER OF EXPRESS
BUILDING, LOOKING SOUTHWEST

OR-168-15 INTERIOR VIEW: NORTHWEST CORNER OF EXPRESS
BUILDING, LOOKING NORTH

OR-168-16 INTERIOR VIEW: SOUTH END OF EXPRESS BUILDING,
LOOKING AT SOUTHWEST CORNER

OR-168-17 INTERIOR VIEW: SOUTH END OF EXPRESS BUILDING,
LOOKING NORTH

OR-168-18 INTERIOR DETAIL VIEW OF DOOR FRAME AND HISTORIC
CULTURAL REMAINS