

HISTORIC AMERICAN BUILDINGS SURVEY  
INDEX TO PHOTOGRAPHS

HABS  
ORE  
9-BEND,  
2-

**BEND RAILROAD DEPOT**  
**(Oregon Trunk Railway Passenger Station)**  
**1160 N.E. Division Street**  
**(At the Foot of Kearney Street)**  
**Bend**  
**Deschutes County**  
**Oregon**

**HABS No. OR-169**

Orrin Russie, Photographer                      April      1998  
Note: 8 x 10 images were enlarged from 4 x 5 negatives

OR-169-1                      AERIAL VIEW OF BEND, OREGON, VIEW LOOKING  
SOUTHWEST

James Norman, Photographer                      February 1999  
Note: 8 x 10 images were enlarged from 4 x 5 negatives

OR-169-2                      GENERAL CONTEXT VIEW OF BEND RAILROAD DEPOT  
LOOKING SOUTHWEST, WITH DEPOT IN FOREGROUND

OR-169-3                      GENERAL CONTEXT VIEW LOOKING NORTHWEST, WITH  
BEND RAILROAD DEPOT IN BACKGROUND

OR-169-4                      GENERAL CONTEXT VIEW LOOKING NORTH, WITH  
DEPOT BUILDING IN BACKGROUND

OR-169-5                      GENERAL VIEW OF DEPOT, LOOKING NORTHWEST

OR-169-6                      GENERAL VIEW OF DEPOT, LOOKING SOUTHWEST

OR-169-7                      GENERAL PERSPECTIVE VIEW OF EAST ELEVATION,  
LOOKING WEST

OR-169-8                      GENERAL PERSPECTIVE VIEW OF SOUTH AND EAST  
ELEVATIONS OF DEPOT, LOOKING NORTHWEST

OR-169-9                      SOUTH ELEVATION OF DEPOT, WITH PORTE COCHERE  
IN FOREGROUND, VIEW LOOKING NORTH



**BEND RAILROAD DEPOT  
(Oregon Trunk Railroad Station)  
HABS No. OR-169  
INDEX TO PHOTOGRAPHS  
(Page 3)**

- OR-169-19           DETAIL VIEW OF HIPPED ROOF CONSTRUCTION AT THE SOUTH WALL OF THE PORTE COCHERE
- OR-169-20           DETAIL VIEW AT CORNER OF TELEGRAPHER'S BAY, WITH CRAFTSMAN BRACKETING, CORNER TREATMENT OF STONEMWORK AND WINDOW CONSTRUCTION
- OR-169-21           DETAIL VIEW AT CORNER OF TELEGRAPHER'S BAY, GROUND LEVEL, SHOWING STONE BELTCOURSE AND WINDOW SILLS
- OR-169-22           DETAIL VIEW OF DATE STONE AT NORTHWEST CORNER OF THE PORTE COCHERE

James Norman, Photographer           February 1999  
Note: 8 x 10 images were enlarged from 4 x 5 negatives

- OR-169-23           INTERIOR VIEW OF WOMEN'S WAITING AREA, SOUTH WALL
- OR-169-24           INTERIOR VIEW OF WOMEN'S WAITING AREA, WEST WALL
- OR-169-25           INTERIOR DETAIL VIEW OF WOMEN'S WAITING AREA, SHOWING EXPOSED ROOF CONSTRUCTION WITH LACQUERED FINISH, DECORATIVE COVE MOLDING AT INTERSECTION OF ROOF AND WALLS, AND INTERIOR FRAMING DETAILS
- OR-169-26           INTERIOR DETAIL VIEW OF WOMEN'S WAITING AREA, LOOKING SOUTH, SHOWING WINDOW CONSTRUCTION AND WALL FRAMING DETAILS
- OR-169-27           INTERIOR VIEW OF RESTROOM AREA, SHOWING THE INTERIOR STUD-WALL FRAMING

**BEND RAILROAD DEPOT  
(Oregon Trunk Railroad Station)  
HABS No. OR-169  
INDEX TO PHOTOGRAPHS  
(Page 4)**

- OR-169-28 INTERIOR VIEW OF TELEGRAPHER'S BAY, EAST WALL,  
SHOWING INTERIOR FINISHES, FRAMING, AND FURRING  
OVER STONework
- OR-169-29 INTERIOR VIEW OF BAGGAGE ROOM, SHOWING WALL  
CONSTRUCTION AND ROOF FRAMING DETAILS
- OR-169-30 INTERIOR DETAIL VIEW OF NORTHWEST CORNER OF  
BAGGAGE ROOM, SHOWING STONework AND DOOR  
FRAMING DETAILS
- OR-169-31 INTERIOR DETAIL VIEW OF BAGGAGE ROOM, AT APEX  
OF HIPPED ROOF
- OR-169-32 DETAIL VIEW OF INTERIOR FINISHES