

HABS  
SC,  
10-CHAR,  
136-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to:

William Blacklock House  
18 Bull Street  
Charleston  
Charleston County  
South Carolina

HABS No. SC-109

Photos SC-109-1 thru SC-109-<sup>10</sup>~~20~~ were previously transmitted to the Library of Congress. The photos below were taken in 1978 for the 1977-79 South Carolina project made possible by grants from the National Endowment for the Arts. Charles N. Bayless, AIA, was the photographer.

- SC-109-12 GENERAL VIEW; SOUTH (FRONT) ELEVATION, FROM SOUTHEAST.  
All window, door and wall arches are of rubbed and gauged red brick. The walls are of brown brick.
- SC-109-13 REAR VIEW; NORTH ELEVATION.  
Terrace is ca. 1970. Note line of former porch roof (not original) and joist seats.
- SC-109-14 WEST ELEVATION, LOOKING SOUTHEAST
- SC-109-15 GROUND FLOOR ENTRY, SOUTH SIDE
- SC-109-16 ENTRY GATES, FRONT OF HOUSE
- SC-109-17 FIRST FLOOR ENTRY, SOUTH SIDE
- SC-109-18 FIRST FLOOR: HALL, LOOKING NORTH TO STAIR HALL
- SC-109-19 FIRST FLOOR SOUTH (MAIN) ENTRY
- SC-109-20 FIRST FLOOR: HALL ARCH DETAIL
- SC-109-21 FIRST FLOOR: VIEW FROM SOUTHWEST ROOM SHOWING MID-19th CENTURY ARCHES
- SC-109-22 FIRST FLOOR: SOUTHEAST ROOM, NORTH WALL
- SC-109-23 FIRST FLOOR: SOUTHEAST ROOM, MANTEL DETAIL (added to house ca. 1970)
- SC-109-24 FIRST FLOOR: SOUTHWEST ROOM, NORTH WALL

(continued on page 2)

WILLIAM BLACKLOCK HOUSE  
Index To Photographs  
HABS No. SC-109 (page 2)

- SC-109-25 FIRST FLOOR: SOUTHWEST ROOM, MANTEL DETAIL (added ca. 1970)
- SC-109-26 FIRST FLOOR: NORTHWEST ROOM, SOUTH WALL
- SC-109-27 FIRST FLOOR: NORTHWEST ROOM, MANTEL DETAIL
- SC-109-28 FIRST FLOOR: STAIR HALL, DOOR TO BASEMENT SHOWING ORIGINAL OPEN STAIRWELL WAINSCOT RUNNING BEHIND DOOR JAMB UNDER STAIR SOFFITT
- SC-109-29 VIEW OF STAIR HALL CEILING FROM FIRST FLOOR
- SC-109-30 SECOND FLOOR: STAIR HALL CEILING FROM LANDING, LOOKING NORTHEAST
- SC-109-31 SECOND FLOOR: STAIR HALL CEILING FROM SOUTH CENTER ROOM
- SC-109-32 SECOND FLOOR: STAIR HALL LANDING FRIEZE AND BALUSTRADE, LOOKING SOUTH
- SC-109-33 SECOND FLOOR: SOUTHEAST ROOM, NORTH WALL
- SC-109-34 SECOND FLOOR: SOUTHEAST ROOM, MANTEL DETAIL (appears to be original)
- SC-109-35 SECOND FLOOR: SOUTHEAST ROOM, WINDOW CASE (door case similar) AND WAINSCOT DETAIL
- SC-109-36 SECOND FLOOR: SOUTHEAST ROOM, CORNICE DETAIL
- SC-109-37 SECOND FLOOR: STAIR HALL, LOOKING WEST
- SC-109-38 SECOND FLOOR: SOUTH CENTER ROOM, DOOR TO SOUTHWEST ROOM (typical center room door, cornice and wainscot)
- SC-109-39 SECOND FLOOR: SOUTH CENTER ROOM, DOOR ENTABLATURE AND CORNICE DETAIL
- SC-109-40 SECOND FLOOR: SOUTHWEST ROOM, NORTH WALL
- SC-109-41 SECOND FLOOR: SOUTHWEST ROOM, MANTEL DETAIL (appears to be original but with some missing ornament)
- SC-109-42 SECOND FLOOR: SOUTHWEST ROOM, WEST WINDOW DETAIL (typical interior paneling of shutter, shutter bar and recessed spandrel throughout house)

(continued on page 3)

WILLIAM BLACKLOCK HOUSE  
Index To Photographs  
HABS No. SC-109 (page 3)

SC-109-43      SECOND FLOOR:    SOUTHWEST ROOM, CORNICE DETAIL  
SC-109-44      SECOND FLOOR:    NORTHWEST ROOM, SOUTH WALL  
SC-109-45      SECOND FLOOR:    NORTHWEST ROOM, MANTEL DETAIL