

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to:

John Mark Verdier House
801 Bay Street
Beaufort
Beaufort County
South Carolina

HABS No. SC-139

Photos SC-139-1 thru SC-139-4 were previously transmitted to the Library of Congress. The photos below were taken in March 1979 for the 1977-79 South Carolina project made possible by grants from the National Endowment for the Arts. Charles N. Bayless, AIA, was the photographer.

- SC-139-5 GENERAL VIEW, FROM SOUTHEAST
- SC-139-6 SOUTH (FRONT) ELEVATION
- SC-139-7 NORTH (REAR) ELEVATION
- SC-139-8 EAST (left) AND NORTH (right) SIDES
- SC-139-9 FRONT ENTRANCE TO FIRST FLOOR HALL
- SC-139-10 DETAIL OF PORTICO PEDIMENT, UPPER FLOOR OF FRONT ELEVATION
- SC-139-11 HALL LOOKING NORTH, FIRST FLOOR. REAR ENTRY IS UNDER STAIR LANDING
- SC-139-12 DECORATIVE HALL ELEMENTS: CORNICE, PILASTER AND ARCH
- SC-139-13 TYPICAL HALL DOOR AND CASE
- SC-139-14 DETAIL OF STAIRWAY, FIRST FLOOR HALL
- SC-139-15 SOUTHEAST ROOM, FIRST FLOOR, NORTH WALL
- SC-139-16 SOUTHEAST ROOM, FIRST FLOOR, WEST WALL: DETAIL OF DOOR AND CASE
- SC-139-17 SOUTHEAST ROOM, FIRST FLOOR, NORTH WALL: DETAIL OF MANTLE
- SC-139-18 SOUTHEAST ROOM, FIRST FLOOR, NORTH WALL: DETAIL OF CORNICE AND OVERMANTLE
- SC-139-19 SOUTHWEST ROOM, FIRST FLOOR, NORTH WALL

(continued on page 2)

JOHN MARK VERDIER HOUSE
HABS No. SC-139 (page 2)

- SC-139-20 SOUTHWEST ROOM, FIRST FLOOR, NORTH WALL: DETAIL OF MANTLE
- SC-139-21 SOUTHWEST ROOM, FIRST FLOOR: DETAIL OF CORNICE
- SC-139-22 NORTHEAST ROOM, FIRST FLOOR, SOUTH WALL
- SC-139-23 NORTHEAST ROOM, FIRST FLOOR, SOUTH WALL: DETAIL OF MANTLE
- SC-139-24 NORTHWEST ROOM, FIRST FLOOR, SOUTH WALL
- SC-139-25 STAIRHALL, SECOND FLOOR, NORTH WALL, SHOWING VENETIAN WINDOW
- SC-139-26 STAIRHALL LANDING, SECOND FLOOR, LOOKING SOUTH INTO SOUTHEAST ROOM
- SC-139-27 STAIRHALL, SECOND FLOOR: DETAIL OF CORNICE
- SC-139-28 SOUTHEAST ROOM, SECOND FLOOR, NORTH WALL
- SC-139-29 SOUTHEAST ROOM, SECOND FLOOR: SOUTH AND WEST WALLS.
(Note double leaf jib door under south (left) window)
- SC-139-30 SOUTHEAST ROOM, SECOND FLOOR, NORTH WALL: DETAIL OF CHIMNEYPIECE
- SC-139-31 SOUTHEAST ROOM, SECOND FLOOR, NORTH WALL: DETAIL OF MANTLE
- SC-139-32 SOUTHEAST ROOM, SECOND FLOOR, NORTH WALL: DETAIL OF CORNICE AND OVERMANTLE
- SC-139-33 SOUTHEAST ROOM, SECOND FLOOR: DETAIL OF TYPICAL DOOR AND CASE
- SC-139-34 SOUTHWEST ROOM, SECOND FLOOR, NORTH WALL
- SC-139-35 SOUTHWEST ROOM, SECOND FLOOR: LOOKING SOUTHEAST INTO SOUTHEAST ROOM
- SC-139-36 SOUTHWEST ROOM, SECOND FLOOR, NORTH WALL: DETAIL OF MANTLE
- SC-139-37 SOUTHWEST ROOM, SECOND FLOOR: DETAIL OF CORNICE
- SC-139-38 NORTHEAST ROOM, SECOND FLOOR, SOUTH WALL. ROOM COMPLETELY WALLED WITH RANDOM WIDTH BOARDS WHICH WERE PAPERED OR PLASTERED OVER. THIS WAS TYPICAL THROUGHOUT HOUSE EXCEPT FOR WOOD paneled walls
- SC-139-39 NORTHWEST ROOM, SECOND FLOOR: DETAIL OF MANTLE

PHOTOCOPY

- SC-139-40 View of the Verdier House taken during the Civil War.
PHOTOCOPY OF OLD PHOTOGRAPH.