

HABS
SC,
10-CHAR,
103-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Thomas Heyward, Jr. House
(Heyward-Washington House)
87 Church Street
Charleston
Charleston County
South Carolina

HABS No. SC-64

Addendum to:

Heyward-Washington House
Charleston
Charleston County
South Carolina

Photos SC-64-1 thru SC-64-8 were previously transmitted to the Library of Congress. The photos below were taken in October 1977 for the 1977-79 South Carolina project made possible by grants from the National Endowment for the Arts. Charles N. Bayless, AIA, was the photographer.

SC-64-9 EAST (FRONT) ELEVATION

SC-64-10 WEST (REAR) ELEVATION

PHOTOCOPIES

SC-64-11 VIEW OF HOUSE AS IT LOOKED IN 1883.
Photocopy of photograph

SC-64-12 POST 1883 VIEW OF HOUSE DURING ITS USE AS A BAKERY SHOP (1883 to 1929).
Photocopy of photograph

HISTORIC AMERICAN BUILDINGS SURVEY

HABS
SC
10-CHAR,
103

INDEX TO PHOTOGRAPHS

**ADDENDUM TO
THOMAS HEYWARD, JR., HOUSE**
(Heyward-Washington House)
87 Church Street
Charleston
Charleston County
South Carolina

HABS No. SC-64
(page 2)

Photographs HABS No. SC-64-1 to HABS No. SC-64-12 were transmitted previously to the Library of Congress.

This recording project of the Carolina Low Country, by photographer Charles N. Bayless, took place between 1970 and 1988. Bayless's work was made possible by several grants from the National Endowment for the Arts during that interval.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Charles N. Bayless, Photographer, var. dates.

- SC-64-13 EAST SIDE, VIEW OF THE ROOF
- SC-64-14 EXCAVATIONS, EAST SIDE SHOWING FOUNDATIONS OF PRE-1740 JOHN MILNER FRAME HOUSE EAST OF SOUTHEAST CORNER OF EXTANT 1770 HOUSE, LOOKING DOWN
- SC-64-15 EXCAVATIONS SOUTHEAST OF HOUSE, LOOKING NORTH
- SC-64-16 EXCAVATIONS, EAST SIDE LOOKING NORTHEAST AT BRICK STEPS AND FOUNDATIONS LOCATED EAST OF THE NORTHEAST CORNER OF THE EXTANT 1770 HOUSE
- SC-64-17 EXCAVATIONS NORTHEAST OF HOUSE, LOOKING EAST
- SC-64-18 EXCAVATIONS SOUTHEAST OF HOUSE, LOOKING SOUTHEAST
- SC-64-19 INTERIOR VIEW, BASEMENT, SOUTH CHIMNEY FROM THE WEST
- SC-64-20 INTERIOR VIEW, BASEMENT, SOUTH CHIMNEY FROM THE EAST
- SC-64-21 INTERIOR VIEW, FIRST FLOOR SOUTHWEST ROOM, WEST WALL
- SC-64-22 INTERIOR VIEW, FIRST FLOOR NORTHWEST ROOM, WEST WALL
- SC-64-23 INTERIOR VIEW, SECOND FLOOR SOUTHWEST ROOM, EAST WALL

THOMAS HEYWARD, JR., HOUSE
HABS No. SC-64
INDEX TO PHOTOGRAPHS
(page 3)

- SC-64-24 INTERIOR VIEW, SECOND FLOOR SOUTHWEST ROOM, MANTLE^{EL} DETAIL OF CENTER FRIEZE BLOCK
- SC-64-25 INTERIOR VIEW, SECOND FLOOR NORTHWEST ROOM, EAST WALL
- SC-64-26 INTERIOR VIEW, SECOND FLOOR NORTHEAST ROOM, DETAIL OF BREAKFRONT
- SC-64-27 INTERIOR VIEW, SECOND FLOOR SOUTHEAST ROOM, WEST WALL
- SC-64-28 INTERIOR VIEW, SECOND FLOOR SOUTHEAST ROOM, WEST WALL, DETAIL OF MANTLE FRETWORK
- SC-64-29 INTERIOR VIEW, SECOND FLOOR SOUTHEAST ROOM, MANTLE^{EL} DETAIL, WITH SCALE
- SC-64-30 INTERIOR VIEW, SECOND FLOOR SOUTHEAST ROOM, WEST WALL DETAIL OF CHIMNEY PIECE FRETWORK IN MAHOGANY
- SC-64-31 INTERIOR VIEW, SECOND FLOOR SOUTHEAST ROOM, WEST WALL DETAIL OF CHIMNEY PIECE CORNICE
- SC-64-32 INTERIOR VIEW, SECOND FLOOR SOUTHEAST ROOM, TYPICAL CORNICE
- SC-64-33 INTERIOR VIEW, SECOND FLOOR SOUTHEAST ROOM, TYPICAL CORNICE RETURN OVER WINDOWS
- SC-64-34 INTERIOR VIEW, SECOND FLOOR SOUTHEAST ROOM, SOUTH WALL
- SC-64-35 INTERIOR VIEW, ATTIC, EAST KING POST, TOP , VIEW FROM NORTHEAST
- SC-64-36 INTERIOR VIEW, ATTIC, EAST KING POST, TOP, VIEW FROM SOUTHWEST SHOWING RIDGE RAFTER
- SC-64-37 INTERIOR VIEW, ATTIC, EAST KING POST, BASE, VIEW FROM NORTHEAST (NOTE: IRON WEDGE AND IRON STRAP PIN)
- SC-64-38 INTERIOR VIEW, ATTIC, EAST KING POST, BASE, VIEW FROM EAST
- SC-64-39 INTERIOR VIEW, ATTIC, EAST KING POST, BASE, VIEW FROM SOUTHEAST
- SC-64-40 INTERIOR VIEW, ATTIC, NORTHWEST HIP RAFTER
- SC-64-41 INTERIOR VIEW, ATTIC, NORTHWEST HIP RAFTER AT WALL BEARING

THOMAS HEYWARD, JR., HOUSE
HABS No. SC-64
INDEX TO PHOTOGRAPHS
(page 4)

SC-64-42 INTERIOR VIEW, ATTIC, NORTH CHIMNEY FRAMING, VIEW FROM
SOUTHEAST