

HABS
SC,
10-CHAR,
63-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to:

Dr. David Ramsey House
92 Broad Street
Charleston
Charleston County
South Carolina

HABS No. SC-13-1

Photos SC-13-1-1 thru SC-13-1-8 were previously transmitted to the Library of Congress. The photos below were taken for the 1977-79 South Carolina project made possible by grants from the National Endowment for the Arts. Charles N. Bayless, AIA, was the photographer.

PHOTO DATE: AUGUST 1977

SC-13-1-9 SOUTH (FRONT) ELEVATION

SC-13-1-10 WEST SIDE

HABS
SC
10-CHAR
63-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

**ADDENDUM TO
DR. DAVID RAMSAY HOUSE**
92 Broad Street
Charleston
Charleston County
South Carolina

HABS No. SC-13-1
(page 2)

Photographs SC-13-1-1 to 13-1-10 were transmitted previously to the Library of Congress.

This recording project of the Carolina Low Country, by photographer Charles N. Bayless, took place between 1970 and 1988. Bayless's work was made possible by several grants from the National Endowment for the Arts during that interval.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Charles N. Bayless, Photographer, July 1981.

SC-13-1-11 INTERIOR, SECOND FLOOR COUNCIL CHAMBERS LOOKING WEST

Charles N. Bayless, Photographer, June 1984.

SC-13-1-12 NORTH SIDE

SC-13-1-13 INTERIOR, FIRST FLOOR SOUTHWEST ROOM, NORTH WALL

SC-13-1-14 INTERIOR, FIRST FLOOR SOUTHWEST ROOM, NORTH WALL CHIMNEYPiece

SC-13-1-15 INTERIOR, FIRST FLOOR SOUTHWEST ROOM, MANTLE ^{el}

SC-13-1-16 INTERIOR, FIRST FLOOR SOUTHEAST ROOM, NORTH WALL

SC-13-1-17 INTERIOR, FIRST FLOOR SOUTHEAST ROOM, MANTLE ^{el} (NOTE: SHELF AND COVE BED MOULD NOT ORIGINAL)

SC-13-1-18 INTERIOR, FIRST FLOOR SOUTHEAST ROOM, LOOKING NORTHWEST TO INCLUDE VIEW OF SOUTHWEST ROOM

SC-13-1-19 INTERIOR, FIRST FLOOR SOUTHEAST ROOM, EAST WALL SHOWING BRICK WALL OF ADJACENT BUILDING

SC-13-1-20 INTERIOR, FIRST FLOOR NORTHWEST ROOM, SOUTH WALL (NOTE: MANTLE ^{el} SHELF NOT ORIGINAL)

SC-13-1-21 INTERIOR, SECOND FLOOR STAIR HALL, LOOKING SOUTH (NOTE: ARCH NOT ORIGINAL TO HOUSE)

DR. DAVID RAMSAY HOUSE
HABS No. SC-13-1
INDEX TO PHOTOGRAPHS
(page 3)

- SC-13-1-22 INTERIOR, SECOND FLOOR HALL, LOOKING NORTHEAST (NOTE: CORNICE;
THIS IS THE CORNICE OF THE ROOM CUT DOWN TO CREATE THE STAIR
HALL CONNECTING THE SECOND AND THIRD FLOORS)
- SC-13-1-23 INTERIOR, SECOND FLOOR SOUTHWEST ROOM, NORTH WALL
- SC-13-1-24 INTERIOR, SECOND FLOOR SOUTHWEST ROOM, EAST WALL
- SC-13-1-25 INTERIOR, SECOND FLOOR SOUTHWEST ROOM, SOUTH WALL
- SC-13-1-26 INTERIOR, SECOND FLOOR SOUTHWEST ROOM, NORTH WALL CHIMNEY
PIECE (NOTE: FALSE RETURNS IN THE CORNICE)
- SC-13-1-27 INTERIOR, SECOND FLOOR SOUTHWEST ROOM, MANTLE^{EL} (NOTE: CORNICE
NOT ORIGINAL)
- SC-13-1-28 INTERIOR, SECOND FLOOR SOUTHEAST ROOM, NORTH WALL (NOTE:
MANTLE^{EL} SHELF AND CORNICE NOT ORIGINAL)
- SC-13-1-29 INTERIOR, SECOND FLOOR SOUTHEAST ROOM, EAST WALL (FRAMING
ORIGINAL)
- SC-13-1-30 INTERIOR, SECOND FLOOR SOUTHEAST ROOM, EAST WALL DOOR DETAIL
OF ADJOINING BUILDING
- SC-13-1-31 INTERIOR, SECOND FLOOR SOUTH WALL (NOTE: MANTLE^{EL} SHELF NOT
ORIGINAL)
- SC-13-1-32 INTERIOR, SECOND FLOOR NORTHEAST ROOM, LOOKING AT NORTHEAST
CORNER AND EAST WALL WINDOW
- SC-13-1-33 INTERIOR, SECOND FLOOR NORTHWEST ROOM, SOUTH WALL (MANTLE^{EL}
SHELF AND CORNICE NOT ORIGINAL)
- SC-13-1-34 INTERIOR, THIRD FLOOR SOUTHWEST ROOM LOOKING NORTH (NOTE:
CHAIR RAIL BLOCKING CENTER DOOR)
- SC-13-1-35 INTERIOR, THIRD FLOOR SOUTHWEST ROOM, SOUTH WALL
- SC-13-1-36 INTERIOR, THIRD FLOOR SOUTHEAST ROOM LOOKING NORTHEAST
- SC-13-1-37 INTERIOR, THIRD FLOOR NORTHWEST ROOM, LOOKING SOUTHEAST
SHOWING CHIMNEY CONSTRUCTION

DR. DAVID RAMSAY HOUSE
HABS No. SC-13-1
INDEX TO PHOTOGRAPHS
(page 4)

SC-13-1-38 INTERIOR, THIRD FLOOR NORTHEAST ROOM, LOOKING NORTHEAST,
SHOWING WINDOW IN EAST WALL (NOTE: THIRD FLOOR NOT ORIGINAL TO
HOUSE)