

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ELLSWORTH AIR FORCE BASE,
AIRMEN'S DORMITORY
(Building No. 1115)
1392 Ellsworth Street
Black Hawk Vicinity
Meade County
South Dakota

HABS No. SD-21-J

Kevin Eilbeck and Roger Slott, Photographers, February, 1996

Note: 4" x 5" images were made from 4" x 5" negatives.

- SD-21-J-1 SOUTHEAST CORNER, VIEW TO NORTHWEST.
- SD-21-J-2 EAST FRONT, VIEW TO WEST.
- SD-21-J-3 NORTHEAST CORNER, VIEW TO SOUTHWEST.
- SD-21-J-4 WEST BACK, VIEW TO EAST.
- SD-21-J-5 INTERIOR VIEW OF ROOM 125 LOOKING AT DOOR TO HALLWAY,
SHOWING CLOSETS & SINK, ON FIRST FLOOR OF SOUTH WING,
VIEW TO SOUTHEAST.
- SD-21-J-6 INTERIOR VIEW OF ROOM 127 LOOKING AT DOOR TO HALLWAY,
SHOWING CLOSETS, ON FIRST FLOOR OF SOUTH WING, VIEW TO
SOUTHEAST.
- SD-21-J-7 INTERIOR VIEW OF ROOM 125 LOOKING AT DOOR TO SHARED
TOILET/SHOWER THROUGH TO ROOM 127, ON FIRST FLOOR OF
SOUTH WING, VIEW TO NORTH.
- SD-21-J-8 INTERIOR VIEW OF ROOM 127 LOOKING AT SINK AND DOOR TO
SHARED TOILET/SHOWER THROUGH TO ROOM 125, ON FIRST
FLOOR OF SOUTH WING, VIEW TO SOUTH.
- SD-21-J-9 INTERIOR VIEW OF CENTRAL LOUNGE AREA LOOKING TOWARD
DOOR TO HALLWAY LEADING TO NORTH WING OF FIRST
FLOOR, VIEW TO NORTH.
- SD-21-J-10 INTERIOR VIEW OF STAIR TOWER ON FIRST FLOOR LEVEL OF
NORTH WING, VIEW TO EAST.

Ellsworth Air Force Base
Airmen's Dormitory
(Building No. 1115)
HABS No. SD-21-J
INDEX TO PHOTOGRAPHS
(Page 2)

- SD-21-J-11 INTERIOR VIEW OF ROOM 115 LOOKING TO NORTHWEST CORNER AT WINDOW OF WEST WALL, ON FIRST FLOOR OF NORTH WING.
- SD-21-J-12 INTERIOR VIEW OF ROOM 114 LOOKING AT CLOSETS, SINK, AND DOOR TO TOILET/SHOWER ROOM, ON FIRST FLOOR OF NORTH WING, VIEW TO SOUTHEAST.
- SD-21-J-13 INTERIOR VIEW OF HALLWAY ON FIRST FLOOR OF NORTH WING, VIEW TO SOUTH.
- SD-21-J-14 INTERIOR VIEW OF BOILER ROOM LOOKING TOWARD EXTERIOR DOOR IN BASEMENT BELOW CENTRAL LOUNGE, VIEW TO SOUTHWEST.
- SD-21-J-15 INTERIOR VIEW OF STORAGE ROOM LOOKING TOWARD NORTH WALL AND WINDOWS ON EAST WALL IN BASEMENT OF NORTHWING, VIEW TO NORTHEAST.
- SD-21-J-16 INTERIOR VIEW OF LAUNDRY ROOM SOUTHWEST CORNER WITH WINDOWS ON WEST WALL AND DOOR TO HALLWAY ON EAST WALL IN BASEMENT OF NORTH WING.
- SD-21-J-17 INTERIOR VIEW OF TOILET LOOKING AT WEST WALL WINDOWS FROM HALLWAY IN BASEMENT OF NORTH WING.
- SD-21-J-18 INTERIOR VIEW OF PERSONAL STORAGE ROOM LOOKING TOWARD DOOR TO HALLWAY IN BASEMENT OF NORTH WING, VIEW TO SOUTHWEST.