

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HUNT-HAWES GROCER COMPANY

HABS TX-3503

(Alarm Supply Building)

508 East Seventh Street

Fort Worth

Tarrant County

Texas

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Michael Bodycomb, photographer, October 1999

TX-3503-1	Front, north side
TX-3503-2	East side
TX-3503-3	Perspective view of south side looking northwest
TX-3503-4	Interior view of first floor looking south
TX-3503-5	Interior view of fourth floor looking northeast
TX-3503-6	Interior view of fourth floor looking west with sliding tin-clad fire door to adjacent building (Tindall Storage Warehouse)
TX-3503-7	Interior detail view of freight elevator and spiral package chute
TX-3503-8	Interior detail of typical column saddle
TX-3503-9	Interior detail of first floor typical framing at column D-5
TX-3503-10	Exterior detail view of second and third floor north facade showing wood, 6/6 double-hung windows
TX-3503-11	Exterior detail view of south side, loading dock canopy showing framing structure
TX-3503-12	Exterior detail view of south side, loading dock canopy showing iron suspension rods
TX-3503-13	Exterior detail view of south side, showing brick cornice, pilasters and steel, 2/2 double-hung windows with obscuring glass

HUNT-HAWES GROCER COMPANY

HABS TX-3503

INDEX TO PHOTOGRAPHS

Page 2

TX-3503-14

Vicinity view with Hunt-Hawes Grocer Company in left of
photograph