

433 Shelton Street (House)  
Danville -  
Pittsylvania County  
Virginia

HABS No. VA-1037

MAP 100  
VA,  
72-VANV,  
3-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY  
MID-ATLANTIC REGION NATIONAL PARK SERVICE  
DEPARTMENT OF THE INTERIOR  
PHILADELPHIA, PENNSYLVANIA 19106

HISTORIC AMERICAN BUILDINGS SURVEY  
 UNITED STATES DEPARTMENT OF THE INTERIOR  
 NATIONAL PARK SERVICE

HABS  
 VA  
 72-DANV,  
 3-

ARCHITECTURAL DATA FORM

STATE VIRGINIA	COUNTY PITTSYLVANIA	TOWN OR VICINITY DANVILLE
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) 433 SHELTON STREET (House)		HABS NO. VA-1037
SECONDARY OR COMMON NAMES OF STRUCTURE		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) 433 Shelton Street		
DATE OF CONSTRUCTION (INCLUDE SOURCE) circa 1925 (1925 City Directory and 1978 HAER Whse. Dst. Inventory)	ARCHITECT(S) (INCLUDE SOURCE) Unknown	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Modest one story dwelling typical of many homes built in the Tobacco Warehouse District in the 1920s. Has always remained a single family residence.		
STYLE (IF APPROPRIATE)		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) (see sketches of floor plan) Cinder block foundation replaced original brick foundation on south and east side; wood joists and floors; dirt crawl space; tin roof; asbestos shingle siding.		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) (see sketches of floor plan)		
EXTERIOR FEATURES OF NOTE Symmetrical design; two-over-two-light double hung sash windows; chimneys; hipped tern roof.		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Central hall, symmetrical floor plan of five rooms - see sketches. Paneling covers plaster in interior rooms.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Back porch enclosed and bathroom added; date unknown. Extensive paneling over plaster walls in all interior rooms in 1982. Cinder block foundation replaced original brick in 1983; distinctive wood porch and railing dismantled in 1983.		
PRESENT CONDITION AND USE The house is in good condition with the exception of the shifting foundation, due to retaining wall movement within six feet of the house. House remained single family residence until purchase in May 1985, due to safety hazard.		
OTHER INFORMATION AS APPROPRIATE Copies of documentation and other material will remain in archives of the National Tobacco-Textile Museum.		
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) 1925 City Directory Tax List, City of Danville Real Estate Assessor's Of 1928 HAER Danville Whse. Dst. Inventory 1960 Factory Insurance Assoc. Map, Mus. Archives 1899 Sanborn Insurance Map, Mus. Archives		
COMPILER, AFFILIATION Samuel W. Price, Executive Director, National Tobacco-Textile Museum	DATE August 7, 1985	

433 SHELTON ST.  
JULY 11, 1965  
SCALE  $\frac{1}{8}'' = 1'-0''$   
VA-1037

