

HABS
VA,
10-BED.V,
1A-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOCRAPHS

Poplar Forest, Summer Kitchen
State Route 661
Forest vicinity
Bedford County
Virginia

HABS No. VA-303-A

Addendum to
Poplar Forest, Summer Kitchen
Near Evington
Bedford County
Virginia

One photograph previously transmitted to the Library of Congress.

Jack E. Boucher, HABS staff photographer March 1986 and April 1987

- VA-303-A-~~2~~³ SOUTH FRONT ELEVATION OF SUMMER KITCHEN (LEFT) AND DAIRY (RIGHT), WITHOUT SCALE (1986)
- VA-303-A-~~3~~⁴ SOUTH FRONT ELEVATION OF SUMMER KITCHEN (LEFT) AND DAIRY (RIGHT), WITH SCALE (1986)
- VA-303-A-~~4~~⁵ SOUTH FRONT ELEVATION OF SUMMER KITCHEN WITH SCALE (1986)
- VA-303-A-~~5~~⁶ SOUTH FRONT ELEVATION OF SUMMER KITCHEN WITHOUT SCALE (1986)
- VA-303-A-~~6~~⁷ GENERAL VIEW EAST FROM ROOFTOP OF POPLAR FOREST TOWARDS SUMMER KITCHEN (FOREGROUND) AND DAIRY; CHIMNEY OF SOUTH TENANT HOUSE BARELY VISIBLE THROUGH TREES; EAST PRIVY BARELY VISIBLE OVER EAST MOUND (1987)
- VA-303-A-~~7~~⁸ PERSPECTIVE VIEW OF SUMMER KITCHEN (FOREGROUND) AND DAIRY FROM SOUTHWEST (1986)
- VA-303-A-~~8~~⁹ GENERAL VIEW OF SUMMER KITCHEN AND DAIRY (FOREGROUND) FROM SOUTHEAST (1986)
- VA-303-A-~~9~~¹⁰ NORTH (REAR) ELEVATION OF SUMMER KITCHEN (RIGHT) AND DAIRY (LEFT); HYPHEN HIDDEN BY BUSH (1986)
- VA-303-A-~~10~~¹¹ EAST GABLE FROM NORTHEAST (1986)
- VA-303-A-~~11~~¹² SOUTH FRONT EXPOSURE OF ROOF SHOWING SHINGLES AND CHIMNEY SECTION (1986)
- VA-303-A-~~12~~¹³ DETAIL VIEW OF SHINGLES, NORTH EXPOSURE, SHOWING LICHEN AND MOSS GROWTH (1986)

- VA-303-A-~~13~~¹⁴ SUNLIGHT THROUGH WEST WINDOW OF SUMMER KITCHEN HIGHLIGHTING
BRICK PATTERN OF FLOOR (1987)
- VA-303-A-~~14~~¹⁵ VIEW OF COOKING FIREPLACE AND LINTEL, WEST ROOM, EAST WALL,
FROM SOUTHWEST (1987)
- VA-303-A-~~15~~¹⁶ CLOSE-UP VIEW OF SOUTH END OF COOKING FIREPLACE (1987)
- VA-303-A-~~16~~¹⁷ GENERAL VIEW IN KITCHEN OF FIREPLACE AND MANTEL, AND HALL
THROUGH HYPHEN TO SUMMER KITCHEN (1986)