

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOS

HABS
VA
45-HORPA
1-

HORSEPASTURE STORE
Intersection of U.S. Route 58
and VA Route 687
Horsepasture
Henry County
Virginia

HABS No. VA-1341

Photographer: Robert A. Ryan

December 1993

- VA-1341-1 SOUTH APPROACH TO THE HORSEPASTURE STORE, LOOKING NORTH;
U.S. HIGHWAY 58 (TOWARD MARTINSVILLE) IS IN THE FOREGROUND
- VA-1341-2 OVERALL VIEW OF THE HORSEPASTURE STORE FROM THE EAST;
U.S. HIGHWAY 58 RUNS FROM LEFT TO RIGHT ACROSS THE VIEW,
WHILE ROUTE 687 RECEDES INTO THE DISTANCE AT THE LEFT
- VA-1341-3 SOUTH (FRONT) AND EAST ELEVATIONS OF THE HORSEPASTURE
STORE; LOOKING NORTHWEST
- VA-1341-4 WEST AND SOUTH ELEVATIONS OF THE HORSEPASTURE STORE,
LOOKING NORTHEAST; A "GREENHOUSE" STRUCTURE CAN BE SEEN
EXTENDING TO THE WEST OF THE STORE AT THE LEFT OF THE VIEW
- VA-1341-5 EAST AND NORTH (REAR) ELEVATIONS OF THE HORSEPASTURE
STORE, LOOKING SOUTHWEST; THE STORE'S TWO OUTBUILDINGS
CAN BE SEEN AT THE RIGHT OF THE VIEW
- VA-1341-6 DETAIL VIEW OF THE PORCH AND STOREFRONT, LOOKING NORTH;
A FORMER PROPRIETOR'S NAME, J.L. ROBERSON, CAN BE SEEN ON
THE LEFT STORE WINDOW, AND THE WORD "GROCERIES" ON THE
RIGHT WINDOW
- VA-1341-7 WEST AND SOUTH FACADES OF THE STORE'S TWO OUTBUILDINGS:
A FERTILIZER SHED AT THE LEFT OF THE VIEW AND THE OUTHOUSE
ON THE RIGHT
- VA-1341-8 INTERIOR VIEW OF THE HORSEPASTURE STORE FROM INSIDE THE
FRONT DOOR; LOOKING TOWARD THE REAR OF THE STORE
- VA-1341-9 GENERAL INTERIOR VIEW FROM THE REAR OF THE STORE: LOOKING
SOUTH FROM THE TOP OF THE STEPS TO THE SECOND FLOOR

INDEX TO PHOTOGRAPHS
HORSE PASTURE STORE
HABS No. VA-1341 (Page 2)

- VA-1341-10 LOOKING NORTHWEST AT THE "COMMUNITY" AREA AT THE CENTER OF THE STORE, AND BEYOND AT THE MAIN SALES COUNTERS ALONG THE WEST WALL; METAL SHEATHING TO PROTECT THE WOOD FLOOR FROM THE FORMER HEATING STOVE CAN BE SEEN IN THE FOREGROUND, AND A WOODEN DRAWER UNIT FOR SEEDS IS BEYOND THE CHAIRS
- VA-1341-11 DETAIL VIEW OF THE ORIGINAL COUNTER AND BUILT-IN MERCHANDISE DRAWERS ALONG THE STORE'S EAST WALL; OPEN SHELVING FOR DRY GOODS CAN BE SEEN ABOVE THE COUNTER; LOOKING NORTHEAST
- VA-1341-12 INTERIOR VIEW OF THE 1930'S LEAN-TO ADDITION, SHOWING THE COMMERCIAL STORAGE SPACE AND THE ADDITION'S ROOF FRAMING; LOOKING NORTH
- VA-1341-13 OVERALL VIEW OF THE SECOND FLOOR MEETING ROOM, LOOKING NORTHWEST; THE OLD ROTATING NAIL CASE AND STORE DISPLAY COUNTERS CAN BE SEEN AT THE CENTER OF THE VIEW; THE STAIRS TO THE ATTIC ARE BEHIND THE NAIL CASE AND THE STAIRS TO THE FIRST FLOOR ARE AT THE RIGHT OF VIEW
- VA-1341-14 DETAIL VIEW OF THE OLD ROTATING NAIL CASE AND GLASS DISPLAY CASES NOW LOCATED IN THE SECOND FLOOR MEETING ROOM; LOOKING SOUTHEAST