

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Curtis Wharf, Hay and Grain Warehouse HABS No. WA-198-F
"O" and Second Streets
Anacortes
Skagit County
Washington

John Stamets, Photographer; WA-198-F-1 through WA-198-F-4,
June 1992.

- WA-198-F-1 Hay and Grain Warehouse, north facade.
- WA-198-F-2 Hay and Grain Warehouse, south facade. Loading
dock has been enclosed.
- WA-198-F-3 Hay and Grain Warehouse, interior. View from
the north, looking south.
- WA-198-F-4 Hay and Grain Warehouse, interior. View from
the south, looking north. Interior of Bottling
Works on the left.

Note: For additional written historical and descriptive
information, please see the main entry for the Curtis
Wharf, HABS No. WA-198.

HABS
WASH,
29-ANAC,
1-F-