

HABS
WASH
39-YAK,
2-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Yakima National Guard Armory (Yakima Armory) HABS No. WA-204
202 South 3rd Street
Yakima,
Yakima County,
Washington.

Note: All photographs in the series listed below are 8" X 10" enlargements from 4" X 5" negatives.

Ken Whitmire, Photographer October 1993 (WA-204-1,2,4-11 and 14)

Michael Cadden, Photographer October 1993 (WA-204-3, 12 and 13)

Ken Whitmire, Photographer November 1993 (WA-204-15 through WA-204-34)

WA-204-1 VIEW OF YAKIMA ARMORY (EAST ELEVATION) FROM SOUTH 3RD STREET FACING WEST.

WA-204-2 VIEW OF NORTH (NORTH ELEVATION) SIDE OF YAKIMA ARMORY FROM EAST WALNUT STREET FACING SOUTH.

WA-204-3 REAR OF YAKIMA ARMORY (WEST ELEVATION) FROM SOUTH 2ND STREET FACING EAST.

WA-204-4 VIEW OF SOUTH SIDE OF YAKIMA ARMORY FACING NORTH.

WA-204-5 VIEW OF YAKIMA ARMORY FROM INTERSECTION OF SOUTH 3RD STREET AND EAST WALNUT STREET LOOKING SOUTHWEST.

WA-204-6 VIEW OF YAKIMA ARMORY FROM VICINITY OF INTERSECTION OF SOUTH 3RD STREET AND EAST SPRUCE STREET LOOKING NORTHWEST.

WA-204-7 DETAIL VIEW OF FRONT ARCH, EAGLE AND BAY WINDOW TAKEN FROM SOUTH 3RD STREET LOOKING WEST.

WA-204-8 DETAIL OF SOUTHERNMOST BAY WINDOW TAKEN FROM SOUTH 3RD STREET FACING WEST.

WA-204-9 DETAIL VIEW OF EAGLE OVER FRONT ARCH TAKEN FROM SOUTH 3RD STREET FACING WEST.

WA-204-10 DETAIL VIEW OF FRIEZE JUST BELOW ROOF PARAPET TAKEN FROM SOUTHEAST CORNER OF BUILDING LOOKING NORTHWEST.

Yakima National Guard Armory
HABS No. WA-204
Index to Photographs (Page 2)

- WA-204-11 VIEW OF FRIEZE SHOWING RELATIONSHIP TO PARAPET TAKEN FROM SOUTHEAST CORNER OF ARMORY LOOKING NORTHWEST.
- WA-204-12 DETAIL VIEW OF FRONT (EAST) CORNER STONE LOCATED AT NORTHEAST CORNER OF BUILDING TAKEN FROM SOUTH 3RD STREET LOOKING WEST.
- WA-204-13 VIEW OF BUILDING SHOWING BOTH CORNERSTONES TAKEN FROM NORTHEAST CORNER LOOKING SOUTH. NOTE BRICKED IN BASEMENT WINDOW WITH CAST IRON LOUVER.
- WA-204-14 VIEW OF NORTH ARCH TAKEN FROM EAST WALNUT STREET
- WA-204-15 VIEW OF 1ST FLOOR HALLWAY AND GRAND STAIRWAY TAKEN FROM SE CORNER LOOKING NW.
- WA-204-16 INTERIOR VIEW OF MAIN ENTRANCE LOOKING EAST ON FIRST FLOOR
- WA-204-17 VIEW OF FIREPLACE AT NORTH END OF HEADHOUSE ON FIRST FLOOR (ORIGINALLY NORTH COMPANY ROOM)
- WA-204-18 VIEW OF DOUBLE DOORS LEADING TO DRILL FLOOR, LOOKING WEST FROM MAIN ENTRY ON FIRST FLOOR
- WA-204-19 DETAIL OF NEWELL POST AT FOOT OF GRAND STAIRWAY FIRST FLOOR
- WA-204-20 VIEW OF NORTH SIDE OF GRAND STAIRWAY FROM FIRST FLOOR LOOKING WEST.
- WA-204-21 VIEW OF GRAND STAIRWAY LOOKING SOUTHWEST FROM THE NORTHEAST CORNER OF THE FIRST FLOOR.
- WA-204-22 VIEW OF GRAND STAIRWAY FROM NORTHEAST HALLWAY OF SECOND FLOOR LOOKING SOUTHWEST.
- WA-204-23 VIEW OF LARGE FIREPLACE SOUTH END OF SECOND FLOOR (SOCIAL HALL) TAKEN FROM DOORWAY LOOKING SOUTH.
- WA-204-24 VIEW OF PICTURE FRAME GRAND STAIRWAY LANDING
- WA-204-25 VIEW OF UPPER PORTION OF GRAND STAIRWAY SHOWING SKY LIGHT, COLUMN CAPITALS AND COFFERED CEILING. PHOTO TAKEN FROM SOUTHWEST CORNER OF SECOND FLOOR LOOKING NORTHEAST.
- WA-204-26 DETAIL OF COLUMN CAPITAL AND COFFERED CEILING - GRAND STAIRWAY

Yakima National Guard Armory
HABS No. WA-204
Index to Photographs (Page 3)

- WA-204-27 DETAIL OF ENGAGED COLUMN CAPITAL ON WEST WALL OF GRAND STAIRWAY
- WA-204-28 VIEW OF SECOND FLOOR DOUBLE DOORS LEADING TO CLASS ROOM (VETERAN'S HALL) AT NORTH END OF BUILDING. SHOWS OAK DOORS, CEILING HEIGHT, GLASS TRANSOM AND ACCESS TO DUMB WAITER AT THE RIGHT OF THE DOOR.
- WA-204-29 DETAIL OF SECOND FLOOR NORTH LATRINE SHOWING TILE FLOOR, COMMODOE STALL AND LOUVERED DOOR TO COMMODOE STALL.
- WA-204-30 VIEW OF DRILL HALL FROM SECOND FLOOR EAST BALCONY FACING WEST. SHOWS ALTERNATE BAY X BRACING OF ROOF TRUSSES. ALSO SHOWS TRUSSES, WINDOWS IN THE MONITOR, STAIRWAY AT THE SOUTHWEST CORNER OF THE DRILL HALL AND THE THREE LEVELS OF BENCHES ON THE BALCONY.
- WA-204-31 VIEW OF DRILL HALL FROM NORTH END OF DRILL FLOOR FACING SOUTH. SHOWS EAST AND WEST BALCONIES, VEHICLE ENTRANCE AT THE SOUTHWEST CORNER OF THE DRILL FLOOR, THE CONCESSION STAND IN THE SOUTHEAST CORNER OF THE DRILL FLOOR AND THE FOUR WINDOWS IN THE SOUTH TRUSS SPACE. NOTE CRACKS IN THE UPPER RIGHT CORNER (WEST) OF THE SOUTH WALL.
- WA-204-32 VIEW OF ROOF TRUSSES FROM SOUTHEAST CORNER OF BALCONY LOOKING NORTHWEST. SHOWS WINDOWS ON WEST MONITOR, WINDOWS IN THE NORTH WALL OF THE DRILL HALL AND STAIRWAY AT THE NORTHWEST CORNER OF THE BALCONY.
- WA-204-33 VIEW OF DRILL HALL FROM NORTHEAST CORNER OF BALCONY LOOKING SOUTHWEST SHOWING WEST BALCONY AND DRILL FLOOR
- WA-204-34 VIEW OF SQUIRREL CAGE VENTILATOR FAN LOCATED IN BASEMENT WHICH CIRCULATES HEATED AIR TO DRILL HALL.
- WA-204-35 PHOTOCOPY OF PHOTOGRAPH. VIEW OF ARMORY FROM INTERSECTION OF SOUTH 3RD AND EAST WALNUT STREET LOOKING SOUTHWEST CIRCA 1917. THIS IS A COPY OF A POST CARD SIZED PRINT LOANED BY THE YAKIMA VALLEY MUSEUM AND HISTORICAL ASSOCIATION. PHOTOGRAPHER UNKNOWN.

Yakima National Guard Armory
HABS No. WA-204
Index to Photographs (Page 4)

WA-204-36

PHOTOCOPY OF PHOTOGRAPH. VIEW OF ARMORY FROM INTERSECTION OF SOUTH 3RD STREET AND EAST WALNUT STREET CIRCA 1937. NOTE PAVED STREETS, STREET LIGHTS AND WINDOWS ON MONITOR OPEN FOR VENTILATION. THIS IS A COPY OF A POST CARD SIZED PRINT LOANED BY THE YAKIMA VALLEY MUSEUM AND HISTORICAL ASSOCIATION. PHOTOGRAPHER UNKNOWN.