

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

SUNRISE LODGE

HABS No. WA-237

Mount Rainier National Park

Longmire vicinity

Pierce County

Washington

John Stamets, photographer, September 1998

- WA-237-1 CONTEXT VIEW LOOKING SOUTHWEST FROM SOURDOUGH RIDGE SHOWS MOUNT RAINIER, SUNRISE LODGE AT CENTER LEFT AND STOCKADE GROUP SLIGHTLY FURTHER AWAY.
- WA-237-2 VISITORS PARKING LOT AS SEEN FROM TRAIL ON SOURDOUGH RIDGE. SUNRISE LODGE AT CENTER; STOCKADE GROUP ON RIGHT.
- WA-237-3 CONTEXT VIEW LOOKING SOUTHEAST FROM DEGE MOUNTAIN TRAIL SHOWS SUNRISE LODGE AT CENTER AND STOCKADE GROUP TO RIGHT.
- WA-237-4 ELEVATION VIEW OF WEST SIDE OF SUNRISE LODGE.
- WA-237-5 ELEVATION VIEW OF EAST SIDE OF SUNRISE LODGE.
- WA-237-6 OBLIQUE VIEW OF SOUTHWEST CORNER OF SUNRISE LODGE.
- WA-237-7 OBLIQUE VIEW OF SOUTHEAST CORNER OF SUNRISE LODGE.
- WA-237-8 UPPER SEGMENT OF FRONT (SOUTH SIDE) OF SUNRISE LODGE.
- WA-237-9 LOWER SEGMENT OF FRONT (SOUTH SIDE) OF SUNRISE LODGE SHOWS ENTRANCE TO RANGER STATION.
- WA-237-10 INTERIOR VIEW OF RANGER STATION, LOOKING NORTHWEST.
- WA-237-11 INTERIOR VIEW OF DINING ROOM, LOOKING SOUTH.
- WA-237-12 INTERIOR VIEW OF DINING ROOM, LOOKING NORTH.
- WA-237-13 INTERIOR VIEW OF NORTHEAST CORNER OF DINING ROOM.
- WA-237-14 INTERIOR VIEW OF KITCHEN, LOOKING WEST.
- WA-237-15 INTERIOR VIEW OF UPSTAIRS DORMITORY, LOOKING SOUTH.