

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

LONGMIRE SERVICE STATION

HABS No. WA-239

(Automotive Service Station, Longmire Springs Historic District)

Mount Rainier National Park

State Route 706

Longmire

Pierce County

Washington

John Stamets, Photographer, September-October 1997

- WA-239-1 CONTEXT VIEW LOOKING NORTHEAST FROM FRON PORCH OF NATIONAL PARK INN, SHOWING PORTION OF LONGMIRE SERVICE STATION ON FAR LEFT AND MOUNT RAINIER IN DISTANCE
- WA-239-2 CONTEXT VIEW LOOKING NORTHEAST, SHOWING PORTION OF SERVICE ROAD AND STATION
- WA-239-3 OBLIQUE VIEW OF NORTHEAST CORNER OF STATION, SHOWING NATIONAL PARK INN IN DISTANCE
- WA-239-4 OBLIQUE VIEW OF NORTHWEST CORNER OF STATION, SHOWING RESTROOM BUILDING IN DISTANCE
- WA-239-5 ELEVATION OF FRONT (NORTH SIDE) OF STATION
- WA-239-6 OBLIQUE VIEW OF REAR (SOUTHEAST CORNER) OF STATION, SHOWING LADDER TO ATTIC APARTMENT
- WA-239-7 OBLIQUE VIEW OF NORTHWEST CORNER OF ATTENDANT'S OFFICE
- WA-239-8 VIEW LOOKING NORTHWEST, SHOWING TWO RESTORED HISTORIC GASOLINE PUMPS
- WA-239-9 DETAIL OF HEAD OF RESTORED HISTORIC GASOLINE PUMP
- WA-239-10 INTERIOR VIEW OF NORTHEAST CORNER OF STATION
- WA-239-11 INTERIOR VIEW OF BACK (SOUTH) WALL OF STATION
- WA-239-12 INTERIOR VIEW LOOKING NORTH IN ATTIC APARTMENT