

## HISTORIC AMERICAN BUILDINGS SURVEY

### INDEX TO PHOTOGRAPHS

ARNOLD FARM, BARN  
1948 Arnold Road  
Coupeville vicinity  
Whidbey Island  
Island County  
Washington

HABS WA-244-A

### INDEX TO BLACK AND WHITE PHOTOGRAPHS

Anne E. Kidd, photographer, April 2006

- WA-244-A-1           VIEW OF MACHINE SHOP STORAGE OPENINGS, NORTH  
END OF BARN, LOOKING SOUTH (This northern-most facade  
of the barn was originally a board and batten wall with two sliding  
doors. In the early decades of the twentieth century Frederick  
Edward Arnold moved the wall and doors; they now make up the  
north end of bay 3. This was done to ease machine storage)
- WA-244-A-2           INTERIOR OF BARN HAYLOFT, LOOKING WEST (Charles  
Arnold added a Cleaning Mill to the barn's hayloft c. 1960. This  
photograph shows the elevator, chaff shoot, and metal funnel that  
still remain. The barn's gambrel roof is supported by a three-hinged  
arch truss system)
- WA-244-A-3           INTERIOR PERSPECTIVE OF HAYLOFT, LOOKING  
SOUTHEAST, WITH VIEW OF POST CONFIGURATION
- WA-244-A-4           INTERIOR OF EAST DOOR, SOUTH WALL, AND AISLE  
LOOKING EAST (This bay of the barn was originally used for  
livestock. Horse pens and milking stanchions remain. Floor was  
built with 1/4 inch gaps between the planks to allow air circulation.  
Photograph also shows the knee-high hinged doors that open for  
easy removal of manure)