

WYO-12

Stable  
Fort Laramie, Wyoming

HABS  
WYO  
8-FOLA,  
3J-

PHOTOGRAPHS  
WRITTEN HISTORIC AND DESCRIPTIVE DATA

Historic American Buildings Survey  
Branch of Plans and Design, Region Two  
National Park Service  
Omaha, Nebraska

## STABLE

Fort Laramie, Wyoming

HABS  
WYO  
2-FOLA  
2J-CUSTODIAN

United States  
Department of the Interior  
National Park Service

DATE OF ERECTION

Erected about 1881

BUILDER

Built by United States Army

PRESENT CONDITION

This building is in very poor condition. The walls have cracked in places. Some of the stones have fallen out of the stone foundation. Part of the wall has been torn out at the door.

The door and part of the frame is missing. The window sash is damaged and glass broken out. The shingles are weathered badly, some of them have blown off.

NUMBER of STORIES

One story.

MATERIAL of CONSTRUCTION

The foundation is constructed of limestone laid with lime mortar. This stone foundation wall extends above the floor line approximately 2' - 4". The wall above the stone foundation is of lime and aggregate (concrete) approximately 1'-0" thick extending to the plate line and into the end gables. This lime concrete wall has been poured on top of the stone in such a manner to indicate the stone may have been the remains of a former building.

The gable roof has 2"x4" rafters with 1" wood sheathing and 4/2 - 16" wood shingles 4 1/2" to the weather.

The floor at present is earth floor and there is no indication of ever being any other floor.

There is remains of a foundation of a former building adjoining this building on the southeast.

*Leslie E. Wilkie*

Leslie E. Wilkie  
Assistant Architect

February 18, 1943