

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

Shelby Iron Works, Iron Master's House
(Horace Ware House (Ruins))
Birmingham Industrial District
Shelby County Route 42
Shelby
Shelby County
Alabama

HAER No. AL-42-A

HAER
ALA
59-SHEL,
1A-

INDEX TO BLACK AND WHITE PHOTOGRAPHS

NOTE: Photographs were taken by Jet Lowe, Spring 1993.

AL-42-A-1 EXTERIOR VIEW, LOOKING SOUTHEAST, WITH FRONT
FACADE AND PORCH. FREE STANDING BRICK GABLED ROOF
SHOWS EVIDENCE OF RECENT FIRE WHICH PARTIALLY
DESTROYED THE PROPERTY WHICH WAS BUILT IN THE
1840S FOR THE THEN IRON MASTER HORACE WARE.

INDEX TO COLOR TRANSPARENCIES

All color xerographic copies were made from a duplicate color
transparency

NOTE: Photographs were taken by Jet Lowe, Spring 1993.

AL-42-A-2 (CT) EXTERIOR VIEW, LOOKING SOUTHEAST.