

HABS
CAL,
34-SAC,
48-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Sacramento City Hall
915 I Street
Sacramento
Sacramento County

HABS No. CA-418

Bob Van Noy, photographer, summer 1981

- CA-418-1 South (main) and east elevations
- CA-418-2 South and east elevations, photographed from slightly more western position
- CA-418-3 Eastern end pavillion of south elevation
- CA-418-4 Eastern end pavillion of south elevation, pediment detail
- CA-418-5 Central pavillion, south elevation
- CA-418-6 Tower detail, center pavillion, south elevation
- CA-418-7 Park in front of city hall HABS CAL, 34-SAC, 48A-1

HISTORIC AMERICAN BUILDING SURVEY

INDEX TO PHOTOGRAPHS

Sacramento City Hall
915 I Street
Sacramento
Sacramento County
California

HABS No. CA -418 Addendum

Ed Andersen, Photographer

July 2002

- CA -418-8 FRONT AND EAST ELEVATIONS AS VIEWED TO THE WEST FROM I STREET.
- CA -418-9 FRONT VIEW OF CITY HALL AS SEEN FROM CAESAR CHAVEZ PARK. VIEW TO THE NORTH.
- CA -418-10 WEST ELEVATION OF HISTORIC CITY HALL AS VIEWED TO THE EAST.
- CA -418-11 FOYER OF HISTORIC CITY HALL. STAR PATTERN IN FLOOR IS COMPOSED OF VARIOUS COLORED POLISHED GRANITE. VIEW TO THE NORTHEAST.
- CA -418-12 FOYER AS SEEN LOOKING BACK TOWARD MAIN ENTRANCE DOORS. VIEW TO THE SOUTHWEST.
- CA -418-13 MAIN FLOOR HALLWAY EXTENDING TO THE EAST FROM THE FOYER. WAINSCOTING IS WHITE MARBLE WITH LIGHT GRAY VEINS. COFFERED DECORATIVE CEILINGS ARE TYPICAL IN PUBLIC AREAS (WHERE PRESERVED) THROUGHOUT THE BUILDING. VIEW TO THE EAST.
- CA -418-14 ELEVATOR AND STAIRWAYS AS SEEN FROM THE REAR OF THE FOYER. VIEW TO THE NORTH.
- CA -418-15 MAIN FLOOR HALLWAY EXTENDING TO THE WEST FROM THE FOYER (LEFT) WITH ELEVATOR AND STAIRWAYS (RIGHT) VIEW TO THE WEST.
- CA -418-16 MAIL FLOOR MEN'S RESTROOM SHOWING MARBLE WAINSCOTING, THRESHOLDS AND FLOOR BORDERS.
- CA -418-17 SECOND FLOOR HALLWAY. COUNCIL CHAMBERS ARE ACCESSED VIA THE DOORS AT THE END OF THE HALL. VIEW TO THE WEST.
- CA -418-18 SECOND FLOOR HALLWAY AS VIEWED TO THE EAST. OFFICES OF MAYOR AND CITY COUNCIL ARE BEYOND THE DOOR AT THE END OF THE HALL.

- CA -418-19 SECOND FLOOR HALLWAY SHOWING ACCESS TO WOMEN'S RESTROOM. VIEW TO THE NORTH.
- CA -418-20 WOMEN'S RESTROOM ON SECOND FLOOR. TYPICAL OCTAGON TILE AND BLACK AND WHITE POLISHED GRANITE UNDERNEATH WINDOWS AT LEFT. VIEW TO THE EAST.
- CA -418-21 DETAIL VIEW OF WOMEN'S RESTROOM SHOWING BLACK AND WHITE POLISHED GRANITE. VIEW TO THE NORTH.
- CA -418-22 MEN'S RESTROOM ON SECOND FLOOR SHOWING OCTAGON TYLE AND POLISHED GRANITE WAINSCOTING. VIEW TO THE SOUTH.
- CA -418-23 FOYER AND ENTRANCE DOORS TO COUNCIL CHAMBERS. VIEW TO THE WEST.
- CA -418-24 COUNCIL CHAMBERS. VIEW TO THE SOUTH.
- CA -418-25 COUNCIL CHAMBERS. VIEW TO THE NORTH.
- CA -418-26 THIRD FLOOR HALLWAY. VIEW TO THE WEST.
- CA -418-27 THIRD FLOOR HALLWAY. VIEW TO THE EAST.
- CA -418-28 THIRD FLOOR OFFICE. DECORATIVE COFFERED CEILING AT TOP WAS ONCE PART OF HALLWAY. VIEW TO THE SOUTH.
- CA -418-29 ABANDONED WATER TANKS IN TOWER OF CITY HALL. VIEW TO THE SOUTHEAST.