

## HISTORIC AMERICAN BUILDINGS SURVEY

### INDEX TO PHOTOGRAPHS

CONSTRUCTION SHOPS (Building 49)  
St. Elizabeths West Campus  
639–661 Birch Street SE  
Washington, D.C.

HABS No. DC-349-V

### INDEX TO BLACK AND WHITE PHOTOGRAPHS

Leslie Schwartz, photographer, August 2010

- DC-349-V-1. View from northeast, Rest/Circulating Library (left) and Fire House (right) in foreground
- DC-349-V-2. East (front) facade, view from east
- DC-349-V-3. View from northwest
- DC-349-V-4. East General Laundry and South Addition, view from southeast
- DC-349-V-5. North (side) facade, view from north
- DC-349-V-6. East Addition, view from northeast
- DC-349-V-7. North facade, view from north
- DC-349-V-8. Laundry Exchange and West Wing, view from west
- DC-349-V-9. Wash Room Annex, view from northwest
- DC-349-V-10. Southwest Addition, view from west
- DC-349-V-11. First floor, South Addition, view from northeast
- DC-349-V-12. Workshop, first floor, General Laundry, view from southwest
- DC-349-V-13. Workshop, first floor, General Laundry, view from northwest
- DC-349-V-14. Workshop, first floor, General Laundry, view from northeast
- DC-349-V-15. Wash Room Annex, view from east
- DC-349-V-16. Paint shop, second floor, General Laundry, view from south
- DC-349-V-17. Sheet metal shop, second floor, General Laundry, view from southeast
- DC-349-V-18. Main space, third floor, General Laundry, view from northwest