

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

WAREHOUSE/LAUNDRY/ANNEX (Building 118/118A)
St. Elizabeths West Campus
Birch Street SE
Washington, D.C.

HABS No. DC-349-BJ

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Leslie Schwartz, photographer, August 2009

- DC-349-BJ-1. South (front) facade and lower and upper truck yards, view from south
- DC-349-BJ-2. Lower truck yard, view from southeast
- DC-349-BJ-3. Ground floor loading dock, view from northwest
- DC-349-BJ-4. West (side) facade, view from west
- DC-349-BJ-5. Rooftop monitors, view from northwest
- DC-349-BJ-6. Annex, view from northeast
- DC-349-BJ-7. Fourth floor laundry, view from south
- DC-349-BJ-8. Fourth floor laundry, view from south
- DC-349-BJ-9. Fourth Floor laundry, view from southeast
- DC-349-BJ-10. Fourth floor laundry, view from southwest
- DC-349-BJ-11. Fourth floor laundry, view from north
- DC-349-BJ-12. Third floor meat storage hallway, view from north
- DC-349-BJ-13. Second floor storage, view from southwest