

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:

HABS PA-1308

LUNDALE FARM, HOUSE

(Samuel Townsend House)

State Route 100 (South Coventry Township)

Pughtown vicinity

Chester County

Pennsylvania

INDEX TO COLOR TRANSPARENCIES

Jack E. Boucher, photographer,

PA-1308-2 (CT) General view

PA-1308-3 (CT) General view

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:
LUNDALE FARM, HOUSE
(Samuel Townsend House)
State Route 100 (South Coventry Township)
Pughtown vicinity
Chester County
Pennsylvania

HABS PA-1308

Photographs HABS PA-1308-1 through HABS PA-1308-3 were previously transmitted to the Library of Congress.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Jack E. Boucher, photographer,

PA-1308-4	Front façade, partial view of setback kitchen wing on east side, south front.
PA-1308-5	Main front façade, south front.
PA-1308-6	Detailed view of front façade including wooden portico supported by four wooden columns, south façade.
PA-1308-7	Facing northwest, closer view of front façade, south front.
PA-1308-8	Facing northeast, view of front façade including view of west side of the house and partial view of setback kitchen wing to the east side, south façade.
PA-1308-9	View of west front, including partial view of north front.
PA-1308-10	Full view of west front, including partial view of north front corner.
PA-1308-11	View of firewood hatch with door closed, located on the west front.
PA-1308-12	View of firewood hatch with door open, on the west front.
PA-1308-13	Full view of north front.
PA-1308-14	Full view of east front.
PA-1308-15	Hallway with view of staircase, facing north, south façade.
PA-1308-16	East view of living room.
PA-1308-17	View of dining room, facing east.
PA-1308-18	View of parlor fireplace, east of hallway.
PA-1308-19	View of parlor fireplace hatch, adjacent to bookcase, door closed.

LUNDALE FARM, HOUSE
HABS PA-1308
INDEX TO PHOTOGRAPHS

PA-1308-20	View of parlor fireplace hatch, with door open.
PA-1308-21	Deep paneled window facing north.
PA-1308-22	Northeast corner, view of corner fireplace and window.
PA-1308-23	View of enclosed winding staircase.