

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Tannery
East bank of Monocacy Creek
Southwest of Ohio Road in
Eighteenth Century Moravian Industrial Area
Bethlehem
Northampton Co.
Pennsylvania

HABS No. PA-1143

Documentation: 16 sheets (1968, before restoration, but original
elements are noted, including site plans, plans,
elevations, section, framing details)
7 exterior photos (1968, before restoration)
18 interior photos (1968, before restoration)
0 data pages

Jack E. Boucher, Photographer Nov. 1968

- PA-1143-1 VIEW FROM SOUTHWEST TO EAST BANK OF MONOCACY CREEK
- PA-1143-2 WEST ELEVATION
- PA-1143-3 SOUTH ELEVATION
- PA-1143-4 VIEW FROM NORTHEAST
- PA-1143-5 EAST ELEVATION
- PA-1143-6 NORTH ELEVATION
- PA-1143-7 WEST ELEVATION (NORTH END), DETAIL OF ORIGINAL POINTING
- PA-1143-8 FIRST FLOOR, VIEW TO NORTH
- PA-1143-9 FIRST FLOOR, VIEW TO SOUTH
- PA-1143-10 FIRST FLOOR, EARLY STONE PAVING AT ENTRANCE TO NORTHEAST ROOM
- PA-1143-11 FIRST FLOOR, NORTHWEST ROOM, REMAINS OF EARLY FIREPLACE FOUNDATION
- PA-1143-12 FIRST FLOOR, CENTRAL HALLWAY, VIEW TO WEST
- PA-1143-13 SECOND FLOOR, VIEW TO SOUTHWEST
- PA-1143-14 SECOND FLOOR, NORTH WALL. TRACES IN PLASTER OF INTERSECTION
BETWEEN NORTH WALL AND LONGITUDINAL PARTITION (NOW MISSING)
- PA-1143-15 SECOND FLOOR, VIEW TO NORTHEAST

(continued)

- PA-1143-16 THIRD FLOOR, ORIGINAL STAIR TO ATTIC, VIEW TO SOUTH
- PA-1143-17 THIRD FLOOR, VIEW TO SOUTH AND ORIGINAL STAIR TO ATTIC
- PA-1143-18 THIRD FLOOR, VIEW OF EARLY WOOD PARTITIONS
- PA-1143-19 THIRD FLOOR, SOUTHWEST ROOM, VIEW OF WEST WALL
- PA-1143-20 THIRD FLOOR, VIEW TO NORTHEAST
- PA-1143-21 ATTIC, VIEW TO SOUTH
- PA-1143-22 ATTIC, VIEW TO NORTH
- PA-1143-23 ATTIC, NORTH WALL
- PA-1143-24 ATTIC, VIEW OF TYPICAL ORIGINAL ROOM FRAMING
- PA-1143-25 ATTIC, VIEW OF TRUSS (NOT ORIGINAL)