

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
VA
7-ARL,
13A-

BUCKINGHAM APARTMENT COMPLEX, Building 12
4007, 4009, 4011 North Fifth Street
Arlington
Arlington County
Virginia

HABS NO. VA-1339-A

PHOTOGRAPHER: (ALL VIEWS) JOHN CALEB SCHWARTZ

MARCH 1994

- VA-1339-A-1 VIEW NORTHEAST NORTH GLEBE ROAD, BUILDING 12 AT UPPER LEFT
- VA-1339-A-2 VIEW SOUTH-SOUTHEAST, BUILDING 12 AT LEFT
- VA-1339-A-3 VIEW NORTH LANDSCAPE WITH BENCH, BUILDING 12 IN BACKGROUND
- VA-1339-A-4 VIEW NORTH-NORTHEAST FRONT 3/4 VIEW OF BUILDING 12
- VA-1339-A-5 VIEW SOUTHEAST, REAR, 3/4 VIEW OF BUILDING 12
- VA-1339-A-6 VIEW NORTH-NORTHEAST SIDE OF BUILDING 12
- VA-1339-A-7 VIEW NORTH BUILDING 12, MAIN ENTRANCE
- VA-1339-A-8 VIEW NORTH-NORTHEAST DETAIL VIEW, QUOINS
- VA-1339-A-9 DETAIL VIEW, NORTH-NORTHEAST, EYEBROW VENT WITH CHIMNEY, BUILDING 12
- VA-1339-A-10 VIEW NORTH-NORTHEAST DETAIL, LIGHT FIXTURE, BUILDING 12
- VA-1339-A-11 VIEW NORTH DETAIL OF FRONT FIRST FLOOR WINDOW, BUILDING 12
- VA-1339-A-12 VIEW SOUTH, DETAIL OF REAR DOOR, BUILDING 12
- VA-1339-A-13 INTERIOR STAIRWAY TO APARTMENTS, BUILDING 12
- VA-1339-A-14 INTERIOR VIEW NORTH, TOWARDS KITCHEN, BUILDING 12
- VA-1339-A-15 INTERIOR NORTH, KITCHEN, BUILDING 12

INDEX TO PHOTOGRAPHS
BUCKINGHAM APARTMENT COMPLEX
HABS NO. VA-1339-A (PAGE 2)


VA-1339-A-16 INTERIOR SOUTH, TOWARDS FRONT WINDOWS,
BUILDING 12

VA-1339-A-17 INTERIOR NORTH, TOWARDS BATHROOM, FROM REAR,
BUILDING 12

VA-1339-A-18 INTERIOR SOUTH, REAR BEDROOM, BUILDING 12

VA-1339-A-19 INTERIOR SOUTH, DETAIL, REAR BEDROOM
DOORKNOB, BUILDING 12

KEY TO PHOTOGRAPHS
BUCKINGHAM APARTMENT COMPLEX
HABS NO. VA-1339-A (PAGE 3)



BUCKINGHAM APARTMENTS ARLINGTON - VIRGINIA	PHOTO KEY INDEX BUILDING 12	HABS no. VA-1339-A
--	--------------------------------	-----------------------